

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 27 S. R. 9 W., W. M. (continued)

CHAINS

I efface all marks on corner and witnesses referring to R. 9 W., and at point of intersection, set a Sandstone 18 x 12 x 7 ins., 12 ins. in the ground for C. C. for Secs. 1 and 12, marked C. C. on W., with 5 grooves on S. and 1 groove on N. faces, from which:

A Fir, 60 ins. diam. bears N. 29° W. 102 lks. dist. mkd:
T. 27 S. R. 9 W. S. 1 B. T.

A Fir, 20 ins. diam. bears S. 52° W. 91 lks. dist. mkd:
T. 27 S. R. 9 W. S. 12 B. T.

June 28, 1897

This information requested from the B.L.M. Survey Records Office and added to our records April, 1971.

Surveyed by Samuel W. Lackland, U. S. Deputy Surveyor, under contract No. 660, dated May 21, 1896.

Survey commenced June 22, 1897.

Survey completed August 9, 1897.