

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion Subdivisional Lines, T. 31 S., R 5 W.

CHAINS

T 31 S R 5 W
 S 18 | S 17
 S 19 | S 20
 1966

N. 4° 43' W., bet. secs. 17 and 18.

Descend 130 ft. along broken W. slope, through heavy timber and dense undergrowth.

41.09

Point for the $\frac{1}{4}$ sec. cor. of secs. 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 31 S R 5 W
 $\frac{1}{4}$
 S 18 | S 17
 1966

from which

A fir, 20 ins. diam., bears N. 80° E., 39 lks. dist., mkd. $\frac{1}{4}$ S17 BT.

A fir, 22 ins. diam., bears S. 82° W., 43 lks. dist., mkd. $\frac{1}{4}$ S18 BT.

Descend 100 ft. over NW. slope.

41.85

Creek, 1 lk. wide, course S. 70° W.; asc. 1,000 ft. over broken SW. slope changing to S. slope.

82.33

Point for the cor. of secs. 7, 8, 17, and 18, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground and in a mound of stone, 2 ft. base, to top, with brass cap mkd.

T 31 S R 5 W
 S 7 | S 8
 S 18 | S 17
 1966

from which

A live oak, 7 ins. diam., bears N. 84° E., 23 $\frac{1}{2}$ lks. dist., mkd. T31S R5W S8 BT.

A live oak, 7 ins. diam., bears S. 23° E., 33 lks. dist., mkd. T31S R5W S17 BT.

A fir, 33 ins. diam., bears S. 42° W., 47 lks. dist., mkd. T31S R5W S18 BT.

A fir, 23 ins. diam., bears N. 25° W., 48 lks. dist., mkd. T31S R5W S7 BT.

Land, mountainous.

Soil, rocky clay with rock outcroppings.

Timber, fir, oak, madrone, cedar, pine, hemlock, dogwood, yew, chinquapin, and alder; undergrowth, fern, salal, poison oak, ceanothus, Oregon grape, huckleberry, blackberry, and reproduction.