

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion Subdivisional Lines, T. 30 S., R. 5 W.

CHAINS

A fir, 16 ins. diam., bears S. 25° E., 9½ lks. dist.,
with scribe marks COR 62 visible on opened blaze.

Land, broken foothills except for creek bottom.

Soil, rocky clay.

Timber, oak, madrone, fir, alder, maple, cedar, dogwood, yew, and
myrtle; undergrowth, poison oak, salal, fern vine maple, hazel,
arrowwood, blackberry, Oregon grape, wild rose, nettle, and repro-
duction.

S. 0° 57' E., bet. secs. 34 and 35

Ascend 460 ft. over N. slope changing to NW. slope, through medium
timber and dense undergrowth.

19.10 Point for the N 1/16 sec. cor. of secs. 34 and 35.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground,
brass cap mkd.

N 1/16
S 34 | S 35
1967

from which

A fir, 7 ins. diam., bears N. 76 3/4° E., 163 lks. dist.,
mkd. N 1/16 S35 BT.

A fir, 5 ins. diam., bears N. 18° W., 52½ lks. dist.,
mkd. N 1/16 S34 BT.

The cor. falls on a spur, slopes W.; also leave timber, edge bears
SE. and W.; enter old burned area.

Descend 30 ft. over SW. slope.

22.20 Bottom of descent, drains S. 75° W.; asc. 170 ft. over NW. slope.

32.00 Spur, slopes S. 55° W.; desc. 220 ft. over S. slope.

38.00 Ravine, drains S. 55° W.; continue along W. slope.

38.20 Point for the ¼ sec. cor. of secs. 34 and 35, at proportionate
distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the
ground, with brass cap mkd.

¼
S 34 | S 35
T 30 S R 5 W
1967

from which

A maple, 7 ins. diam., bears N. 12¼° E., 9 lks. dist.,
mkd. ¼ S35 BT.

A maple, 13 ins. diam., bears N. 80½° W., 204 lks. dist.,
mkd. ¼ S34 BT.

Descend 260 ft. along W. slope changing to broken SW. slope.

55.90 High voltage transmission line, bears N. 80° W. and S. 80° E.