

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 29 S., R. 5 W.

CHAINS

A cedar snag, 58 ins. diam., bears N. 60° W., 82 lks. dist., with scribe marks S $\frac{1}{4}$ S10 CS BT visible on open double blaze.

S 89° 39' W., on the S. bdy. of sec. 10.

Descend 2 ft. over SW. slope, across old logged area and through dense undergrowth.

.20 Creek, 4 lks. wide, course S. 25° W.; asc. 90 ft. over SE. slope.

5.30 Top of ascent, slopes S.; desc. 240 ft. along broken S. slope.

39.81 True point for the closing cor. of secs. 15 and 16, hereinafter described.

40.35 Point for the cor. of secs. 9 and 10 only, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked

T 29 S R 9 W
S 9 S 10
S 16
1968

from which

A burned fir stump, 35 ins. diam., bears N. 63° E., 23 lks. dist., mkd. T29S R9W S10 BT.

A fir, 56 ins. diam., bears N. 38° W., 70 lks. dist., mkd. T29S R9W S9 BT.

From the cor. of secs. 15, 16, 21, and 22, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1959, monumented with an iron post, 36 ins. long. 1 $\frac{1}{2}$ ins. diam., firmly set, 28 ins in the ground, in center of remains of the original corner tree, a fir root crown, 50 ins. diam., with brass cap marked

DOUG. COUNTY SURVEYORS OFFICE

T 29 S R 9 W
S 16 S 15
S 21 S 22
1959
Coos Co.

from which the remains of the original bearing trees:

A root hole, bears S. 65° E., 27 lks. dist.

A sawed hemlock stump, 32 ins. diam., bears S. 38° W., 42 lks. dist., with scribe marks T29S R9W S2 B visible on open blaze.

A sawed fir stump, 52 ins. diam., bears N. 43° W., 30 lks. dist., with scribe marks T29S R 16 visible on open blaze (Record, 40 lks.)

and bearing trees marked by Byron:

A fir, 12 ins. diam., bears N. 68° E., 67 lks. dist., with healed double blaze.