

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 29 S., R. 9 W.

CHAINS

A chinquapin, 5 ins. diam., bears S. 70° E., 82 lks. dist.,
mkd. T29S R9W S15 CC BT.

A fir, 12 ins. diam., bears S. 64° W., 120 lks. dist.,
mkd. T29S R9W S16 CC BT.

From this point the cor. of secs. 9 and 10 only, bears S. 89° 39' W.,
0.54 chs. dist.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, maple, alder, chinquapin, and willow;
undergrowth, young timber, huckleberry, hazel, arrowwood, thimble-
berry, salmonberry, ceanothus, Oregon grape, salal, and fern.

From the cor. of secs. 9 and 10 only.

N. 0° 19' W., bet. secs. 9 and 10.

Ascend 215 ft. over S. slope changing to SW. slope, through dense
undergrowth, along the W. edge of old logged area.

- 14.30 Top of ascent, slopes W.; desc. 50 ft. over NW. slope.
- 18.50 Bottom of descent, slopes W.; asc. 90 ft. over SW. slope.
- 23.80 Top of ascent, slopes W.; desc. 95 ft. over NW. slope.
- 28.80 Creek, 2 lks. wide, course NW.; desc. 20 ft. over NW. slope.
- 31.00 Creek, 6 lks. wide, course S. 30° W.; asc. 135 ft. over SE. slope.
- 39.41 Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 10, at proportionate
distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long. 2 $\frac{1}{2}$ ins. diam., 24 ins. in the
ground, with brass cap marked

$\frac{1}{4}$
S 9 | S 10
T 29 S R 9 W
1968

from which

A cedar, 14 ins. diam., bears S. 75° E., 183 lks. dist.,
mkd. $\frac{1}{4}$ S10 BT.

A hemlock, 9 ins. diam., bears S. 79° W., 161 lks. dist.,
mkd. $\frac{1}{4}$ S9 BT.

Ascend 200 ft. over SE. slope.

- 51.50 Ridge, bears E. and W.; desc. 460 ft. over general N. slope.
- 54.30 Gravelled road, 35 lks. wide, bears N. 80° W. and S 80° E.
- 69.20 Creek, 4 lks. wide, course N. 65° W.; asc. 55 ft. along W. slope.
- 76.00 Spur, slopes NW.; desc. 120 ft. over N. slope.