

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the W. Bdy., T. 22 S., R. 7 W.

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked

T 22 S
R 8 W R 7 W
S 1 S 6
S 12 S 7
1968

*FD-7/85
L. Roberts
M 90-74*

from which

A hemlock, 5 ins. diam., bears S. 22° E., 21 lks. dist., mkd. T22S R7W S7 BT.

Deposit the corner stone alongside the iron post.

Land, rolling hills.
Soil, sandy clay loam.
Timber, fir, white oak, maple, cedar, and alder; undergrowth, arrowwood, hazel, blackberry, Oregon grape, poison oak, and salal.

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 22 S., R. 7 W., Willamette Meridian, Oregon

(Restoring the 1855 survey by Harvey Gordon and Charles T. Gardner and the 1871 survey by William H. Byars.)

The cor. of secs. 7, 8, 17, and 18, perpetuated and recorded by Wilford N. Haines, Registered Land Surveyor, No. 239, in 1961, munumented with a T shaped iron rod, 36 ins. long, firmly set 30 ins. in the ground, from which the original bearing trees:

A fir, 47 ins. diam., bears N. 51° E., 108 lks. dist., with no marks visible on opened blaze. (Record and slope dist., 118 lks.)

A fir, 55 ins. diam., bears S. 63° E., 82 lks. dist., with healed blaze. (Record, S. 60° E.)

A fir, 47 ins. diam., bears N. 13° W., 24 lks. dist., with fragmentary scribe marks visible on opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap marked

T 22 S R 7 W
S 7 S 8
S 18 S 17
1968

No suitable tree available within limits in sec. 18.

Deposit the iron rod alongside the ironpost.

S 89° 59' W., bet. secs. 7 and 18, marking and blazing the true line.

Ascend 500 ft. over NE. slope, through scattered timber and dense undergrowth.