

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion Subdivisional Lines, T. 22 S., R. 7 W.

CHAINS

A white fir, 5 ins. diam., bears S. 76° W., 18 lks. dist., mkd. T22S R7W S18 CC BT.

From this point the NW. cor. of Cliam 43, bears N. 0° 16' W. 11.35 chs. dist., hereinafter described.

Descend 10 ft. over SW. slope.

57.85 Creek, 2 lks. wide, course S.; asc. 55 ft. over SE. slope.

60.21 Point for the W 1/16 sec. cor. of secs. 7 and 18.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked

W 1/16 $\frac{S 7}{S 18}$
1968

from which

A white oak, 6 ins. diam., bears N. 49° E., 102 lks. dist., mkd. W 1/16 S7 BT.

A white oak, 8 ins. diam., bears S. 45° E., 68 lks. dist., mkd. W 1/16 S18 BT.

Ascend 10 ft. over sSE. slope.

61.00 Spur, slopes S. 30° W., desc. 145 ft. over SW. slope.

78.70 The cor. of secs. 7, 12, 13, and 18.

Land, rolling hills.

Soil, sandy clay loam. Timber, fir, hemlock, white fir, whiteoak, cedar, maple, alder, & willow; undergrowth, vine maple, hazel, poison oak, salmonberry, thimbleberry, arrowwood, salal, & Ore. grape.

From the cor. of secs. 7, 8, 17, and 18.

N. 1° 30' E., bet. secs. 7 and 8.

Descend 250 ft. over NE. slope, through scattered timber and dense undergrowth.

12.60 Creek, 8 lks. wide, course S. 40° E.; asc. 360 ft. over SW. slope.

38.40 Point for the ¼ sec. cor. of secs. 7 and 8, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap marked

$\frac{1}{4}$
S 7 | S 8
T 22 S R 7 W
1968

from which

A fir, 5 ins. diam., bears S. 14° E., 59 lks. dist., mkd. ¼ S8 BT.

No suitable tree available within limits in sec. 7.

From this point a corner established and recorded by Wilford N. Haines, Registered Land Surveyor, No. 239, in 1963, bears S. 68° W., 0.09 chs. dist., monumented with a T shaped iron rod, 36 ins. long, firmly set 24 ins. in the ground, from which