

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey Birs. Claims No. 40 and 44, T. 22 S., Rs. 7 &amp; 8 W.

## CHAINS

A root hole, bears S. 60° E., 45 lks. dist., alongside of which is a fallen white oak, 25 ins. diam., with no marks remaining on opened and rotted blaze.

A stump hole, bears S. 5° W., 68 lks. dist.

At the corner point

Remove the stump of the original corner tree and set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

T 22 S R 8 W

S 12 | C 40  
1968

from which new bearing trees

A fir, 11 ins. diam., bears S. 33° E., 53 lks. dist., mkd. T22S R8W C40 BT.

A fir, 13 ins. diam., bears N. 68° W., 29 lks. dist., mkd. T22S R8W S12 BT.

N. 89° 58' E., along the N. bdy. of Claim No. 40.

Descend 20 ft. over SE. slope, through scattered timber and dense undergrowth.

8.00 Bottom of descent, slopes S., also enter pasture land, edge bears NE. and SW.; asc. 115 ft. over SW. slope.

31.29 Intersect the line bet. secs. 7 and 12, T. 22 S., Rs. 7 and 8 W.,

Point for the closing cor. of secs. 7 and 12, hereinbefore described.

From this point the  $\frac{1}{4}$  sec. cor. of secs. 7 and 12 bears N. 0° 02' W., 4.79 chs. dist., hereinbefore described.

N. 89° 58' E., along the N. bdy. of Claim No. 44, T. 22 S., R. 7 W. beginning new measurement.

Ascend 75 ft. over SW. slope.

7.49 The NE. cor. of Claim No. 44.

Subdivision of Section 7, T. 22 S., R. 7 W.  
Willamette Meridian, Oregon

From the  $\frac{1}{4}$  sec. cor. of secs. 6 and 7.

S. 3° 59' W., on the N. and S. center line of sec. 7.

Ascend 20 ft. over NE. slope, through heavy timber and dense undergrowth.

1.00 Ridge, bears N. 80° W. and S. 80° E.; desc. 820 ft. over SW. slope.

37.00 Creek, 4 lks. wide, course S. 35° E.; asc. 50 ft. over NE. slope.

38.80 Point for the center  $\frac{1}{4}$  sec. cor. of sec. 7, at intersection with the E. and W. center line.