

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 8 W.

CHAINS

The original corner stone is alongside the iron post; a sandstone, 14 x 12 x 6 ins. marked with 4 grooves on the S. face and 1 notch on the E. edge.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, maple, madrone, chinquapin, myrtle, alder and willow; undergrowth, huckleberry, poison oak, arrowwood, hazel, vine maple, thimbleberry, ceanothus, wild rose, Oregon grape, salal, and fern.

N. 0° 08' E., along the W. bdy. of sec. 12.

Descend 370 ft. over broken NW. slope, through scattering timber and dense undergrowth.

18.735 Point for the S 1/16 sec. cor. of sec. 11 only.

Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap marked

S 1/16 |  
S 11 |  
1967

from which

A cedar, 30 ins. diam., bears N. 83° W., 43 lks. dist., mkd. S 1/16 S11 BT.

A cedar, 15 ins. diam., bears S. 63° W., 129 lks. dist., mkd. S 1/16 S11 BT.

Descend 20 ft. along W. slope.

28.75 Bottom of descent, slopes W.; asc. 25 ft. over SW. slope.

34.65 Spur, slopes NW.; desc. 100 ft. over N. slope.

39.07 Point for the ¼ sec. cor. of sec. 11 only, at midpoint latitudinally, on the E. bdy. of the section.

Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap marked

¼ |  
S 11 |  
T 23 S | R 8 W  
1967

from which

A white fir, 15 ins. diam., bears N. 89° W., 100 lks. dist., mkd. ¼ S11 BT.

A white fir, 6 ins. diam., bears S. 69° W., 42 lks. dist., mkd. ¼ S11 BT.

Descend 70 ft. over N. slope.

39.80 Mehl Creek Road, 30 lks. wide, bears N. 80° W. and S. 80° E.; enter pasture, edge bears same as road.

40.00 Record distance for the ¼ sec. cor. of sec. 12 only, there is no remaining evidence of the original corner.