

14436 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 8 W.

CHAINS

38.75 Creek, 1 lk. wide, course S. 40° W.; asc. 15 ft. over SE. slope.

39.70 The ¼ sec. cor. of sec. 10 only, perpetuated and recorded by Vernon Tracey, Deputy County Surveyor, in 1967, monumented with an iron post, 1½ ins. diam., firmly set, projecting 8 ins. above ground, with brass cap marked

COUNTY SURVEYORS OFFICE
T 23 S
¼ S 10 S 11
R 8 W
1967

from which the original bearing trees

A cedar, 25 ins. diam., bears S. 78° E., 86 lks. dist., with fragmentary scribe marks visible on opened and rotted blaze

A root hole, bears N. 76° W., 56 lks. dist., alongside of which is a down fir, 36 ins. diam., no marks visible.

and bearing trees marked by Tracey

A cedar, 23 ins. diam., bears S. 52° E., 3¼ lks. dist., with scribe marks ¼ S11 CS BT visible on open blaze.

A cedar, 6 ins. diam., bears S. 45° W., 67 lks. dist., with scribe marks ¼ S10 CS BT visible on opened blaze.

Add marks BLM 1967 to brass cap.

N. 0° 08' E., beginning new measurement.

Ascend 25 ft. over SE. slope.

1.02 Point for the ¼ sec. cor. of sec. 11 only, at midpoint latitudinally, on the W. bdy. of the section.

Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap marked

¼	S 11
T 23 S	R 8 W
1967	

from which

A fir, 40 ins. diam., bears N. 28° E., 75 lks. dist., mkd. ¼ S11 BT.

A white fir, 8 ins. diam., bears S. 12° E., 67 lks. dist., mkd. ¼ S11 BT.

Ascend 750 ft. over broken SE. slope.

33.00 Ridge, bears N. 80° W. and S. 80° E.; desc. 240 ft. over NE. slope.

40.08 The cor. of secs. 3 and 10 only, perpetuated and recorded by J. W. Byron, Deputy County Surveyor, in 1959, monumented with an iron post, 1½ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap marked

COUNTY SURVEYORS OFFICE
S 3 | S 11
S 10 |
T 23 S | R 8 W
1959