

# County Surveyor's Record, Douglas County, Oregon

14462

Dependent Resurvey, Portion of Subdivisional Lines, T. 27 S., R. 4 W.

CHAINS	
69.80	Spar, slopes S. 15° W.; desc. 300 ft. over broken W. slope.
79.20	The cor. of secs. 26, 27, 34, and 35.  Land, mountainous. Soil, clay loam. Timber, fir, hemlock, cedar, alder, maple, yew, and oak; undergrowth, fern, salal, vine maple, hazel, and Oregon grape.
	N. 0° 26' W., bet. secs. 26 and 27.  Descend 20 ft. over NW. slope, through scattering timber and dense undergrowth.
10.55	Creek, 2 lks. wide, in curve from N. 30° W. to S. 38° W.; asc. 30 ft. over broken N. slope.
14.30	Same creek, 2 lks. wide, course S. 22° W.; asc. 60 ft. over broken N. slope.
19.52	Same creek, 2 lks. wide, course S. 25° E.; asc. 315 ft. over broken N. slope.
36.75	Dirt road, 15 lks. wide, bears N. 75° E. and S. 75° W.
40.33	The $\frac{1}{4}$ sec. cor. of secs. 26 and 27, perpetuated and recorded by the Douglas County Surveyor's Office in 1963, monumented with an iron post, 1 $\frac{1}{2}$ ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.
	<p>COUNTY SURVEYORS OFFICE T 27 S S   S <math>\frac{1}{4}</math> 27   26 R 4 W 1963</p>
	from which the original bearing trees:
	A sawed fir stump, 38 ins. diam., bears N. 88° E., 10 lks. dist., with axe marks visible on decayed blaze.
	A pine stump, 20 ins. diam., bears S. 2° W., 36 lks. dist., with fragmentary scribe marks visible on decayed blaze.
	and bearing trees mkd. by the County Surveyor's Office in 1963
	A fir, 11 ins. diam., bears S. 22° W., 122 lks. dist., with healed blaze.
	A cedar, 21 ins. diam., bears N. 72 $\frac{1}{2}$ ° W., 156 lks. dist., with scribe marks $\frac{1}{4}$ S27 CS BT visible on open blaze.
	Land, Mountainous. Soil, clay loam. Timber, fir, hemlock, cedar, alder, and oak; undergrowth, hazel, salal, fern, and Oregon grape.