

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 33 S., R. 7 W.

CHAINS

A fir, 18 ins. diam., bears S. 15° E., 41 lks. dist.,  
with pitched over blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the  
ground, with brass cap mkd.

T 33 S R 7 W  
¼ S 13  
S 24  
1969

Deposit iron pipe inside the iron post.

S. 89° 26' W., beginning new measurement.

Descend 610 ft. over SW. slope.

11.10 Creek, 1 lk. wide, course N. 60° W.; asc. 25 ft. over NW. slope.

26.35 Creek, 1 lk. wide, course N.; asc. 20 ft. over NE. slope.

29.10 Spur, slopes N.; desc. 115 ft. over NW. slope.

34.85 Creek, 1 lk. wide, course N. 10° W.; asc. 150 ft. over NE. slope.

38.97 The cor. of secs. 13, 14, 23 and 24, occupied by the original  
corner tree, a fir, 42 ins. diam., with illegible scribe marks visible  
on bark blazes on NE. and SE. faces, from which the original bearing  
trees:

A pine, 30 ins. diam., bears N. 55½° E., 98 lks. dist.,  
with healed blaze. (Record, N. 50° E., 111 lks.)

A stump hole, bears S. 40° E., 39 lks. dist.

A decayed fir stump, 14 ins. diam., bears S. 37° W., 32 lks.  
dist., with no marks remaining. (Record, S. 55° W., 34 lks.)

A sawed fir stump, 21 ins. diam., bears N. 34° W., 50 lks. dist.,  
with healed blaze. (Record, N. 36° W., 48 lks.)

and bearing trees mkd. by Richard L. Templin, Jr., Registered  
Engineer, No. 3024, in 1955

A fir, 22 ins. diam., bears S. 15° E., 68 lks. dist.,  
with healed blaze.

A fir, 26 ins. diam., bears N. 20° W., 106 lks. dist.,  
with healed blaze.

and a new bearing tree and reference monument

A fir, 18 ins. diam., bears S. 86° W., 38 lks. dist.,  
mkd. T33S R7W S23 BT.

An iron post, 28 ins. long, 2½ ins. diam., set 24 ins. in  
the ground, bears N. 45° W., 19½ lks. dist., with  
brass cap mkd. T33S R7W S14 RM 19½ lks. 1969 and an arrow  
pointing to the corner.