

Dependent Resurvey, Portion of Subdivisional Lines, T. 33 S., R. 7 W.

CHAINS

Descend 225 ft. over broken SW. slope.

54.60 Creek, 5 lks. wide, course N. 60° W.; asc. 315 ft. over NE. slope.

76.50 Top of ascent, slopes N.; desc. 40 ft. over NW. slope.

79.08 The original cor. of secs. 1, 2, 11, and 12, perpetuated and recorded by Marvin C. Ramsey, Registered Land Surveyor, No. 404, in 1965, with an iron pipe, 2 ins. diam., firmly set, projecting 8 ins. above ground, from which the original bearing trees:

A sawed fir stump, 16 ins. diam., bears N. 35° E.,
73 lks. dist., with no marks visible. (Record, 78 lks.)

A fir, 36 ins. diam., bears S. 86° E., 24 lks. dist.,
with illegible scribe marks visible on bark blaze.

The root crown of a fir, size indeterminate, bears S. 78° W.,
38 lks. dist.

A root hole bears N. 76° W., 34 lks. dist., with a down fir,
18 ins. diam., alongside, with scribe marks
T33S R7 visible on bark blaze.

and bearing trees mkd. by Ramsey

A sawed fir stump, 34 ins. diam., bears N. 59° E., 87 lks.
dist.; with scribe marks T33S R7W S1 RS 404 BT visible
on open blaze.

A fir, 28 ins. diam., bears S. 57° W., 41 lks. dist.,
with healed blaze.

A fir, 26 ins. diam., bears N. 84° W., 185 lks. dist.,
with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the
ground, with brass cap mkd.

T 33 S R 7 W
S 2 | S 1
S 11 | S 12
1969

Reset iron pipe alongside iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, pine, cedar, madrone, oak, alder, and
chinquapin; undergrowth, vine maple, whitethorn, ceanothus,
manzanita, devil's club, and poison oak.

N. 0° 10' E., bet. secs. 1 and 2.

Descend 380 ft. over NW. slope, across logged area, through
dense undergrowth.

10.15 Creek, 5 lks. wide, course W.; asc. 45 ft. over SW. slope.

11.15 Dirt road, 15 lks. wide, bears E. and W.

13.10 Dirt road, 10 lks. wide, bears N. 20° E. and S. 20° W.