

County Surveyor's Record, Douglas County, Oregon

14.182

Dependent Resurvey, Portion of Subdivisional Lines, T. 33 S., R. 7 W.

Douglas County
Spitzer

CHAINS

Ascend 405 ft. over general E. slope, through heavy timber and moderate undergrowth.

- 4.85 Dirt road, 15 lks. wide, bears N. and S.
- 16.40 Ravine, drains S. 60° E.; asc. 255 ft. over broken E. slope.
- 24.50 Spur ridge, bears N. 25° W. and S. 25° E.; desc. 120 ft. over broken S. slope.
- 33.80 Bottom of descent, slopes S.; asc. 35 ft. over broken S. slope.
- 39.85 The cor. of secs. 29, 30, 31 and 32.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, pine, madrone, alder, chinquapin, oak, cedar;
undergrowth, manzanita, vine maple, devil's club, whitethorn,
ceanothus, and poison oak.

Subdivision of Sec. 1, T. 33 S., R. 7 W.,
Willamette Meridian, Oregon

From the $\frac{1}{4}$ sec. cor. of secs. 1 and 12.

N. 0° 04' E., on the N. and S. center line of sec. 1.

Ascend 195 ft. over SW. slope, through scattering young timber and dense undergrowth.

- 6.60 Dirt road, 30 lks. wide, bears E. and W.
- 14.60 Spur, slopes S. 45° W.; desc. 50 ft. over NW. slope.
- 18.80 Ravine, drains N. 70° W.; asc. 20 ft. over SW. slope.
- 19.70 Top of ascent, slopes W.; desc. 20 ft. over NW. slope.
- 20.50 Ravine, drains S. 45° W.; asc. 50 ft. over S. slope.
- 21.185 Point for the center S $\frac{1}{16}$ sec. cor. of sec. 1.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} C \\ S \frac{1}{16} | S \frac{1}{16} \\ C \\ 1969 \end{array}$$

from which

A madrone, 4 ins. diam., bears N. 85° E., 21½ lks. dist., mkd. X BT.

A pine, 6 ins. diam., bears N. 8½° W., 14½ lks. dist., mkd. CS $\frac{1}{16}$ S1 BT.

Ascend 385 ft. over S. slope, changing to SW. slope.

- 38.50 Ridge, bears N. 65° W. and S. 65° E.; desc. 125 ft. over NE. slope, Enter heavy timber, edge bears N. 65° W. and S. 65° E.
- 42.37 Point for the center $\frac{1}{4}$ sec. cor. of sec. 1, at intersection with the E. and W. center line.