

County Surveyor's Record, Douglas County, Oregon

14504

Dependent Resurvey, Portion of Subdivisional Lines, T. 31 S., R. 7 W.

CHAINS	
	N. 89° 57' W., beginning new measurement. Ascend 95 ft. over NE. slope
4.15	Ridge, bears N. 30° W., and S. 30° E.; also jeep road, 10 lks. wide, bears same as ridge; desc. 275 ft. over SW. slope.
14.15	Ravine, drains S. 40° W.; desc. 185 ft. over broken SW. slope.
26.90	Ravine, drains S. 30° W.; desc. 215 ft. over SW. slope.
39.43	The cor. of secs. 11, 12, 13, and 14. Land, mountainous. Soil, rocky clay loam. Timber, fir, hemlock, cedar, pine, oak, and alder; undergrowth, salal, fern, hazel, poison oak, and Oregon grape.
	N. 1° 48' W., bet. secs. 11 and 12. Descend 80 ft. over NW. slope, through moderate timber and dense undergrowth.
3.80	Creek, 2 lks. wide, course S. 55° W.; asc. 390 ft. over SW. slope.
18.05	Spur, slopes S. 70° W.; desc. 15 ft. over NW. slope.
20.45	Ravine, drains S. 45° W.; asc. 130 ft. over SW. slope.
23.45	Top of ascent, slopes W.; desc. 145 ft. over NW. slope
29.55	Ravine, drains W.; asc. 110 ft. over SW. slope.
34.40	Ridge, bears N. 45° W., and S. 45° E., also jeep road, 10 lks. wide, bears same as ridge, desc. 125 ft. over NE. slope.
40.63	Point for the $\frac{1}{4}$ sec. cor. of secs. 11 and 12, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> $\frac{1}{4}$ S 11 S 12 T 31 S R 7 W 1969 </div> from which A fir, 7 ins. diam., bears S. 54 $\frac{3}{4}$ ° E., 37 $\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S12 BT. A fir, 13 ins. diam., bears S. 65 $\frac{1}{4}$ ° W., 31 lks. dist., mkd. $\frac{1}{4}$ S11 BT.
	Descend 55 ft. over NE. slope.
44.70	Ravine, drains E.; asc. 20 ft. over SE. slope.
49.35	Spur, slopes N. 45° E.; desc. 285 ft. over N. slope.
64.20	Creek, 1 lk. wide, course N. 60° E.; desc. 85 ft. over N. slope.