

# County Surveyor's Record, Douglas County, Oregon 14520

Dependent Resurvey, Portion of Subdivisional Lines, T. 30 S., R. 2 W.

**CHAINS**

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 30 S R 2 W  
 $\frac{S\ 6}{S\ 7} | \frac{S\ 5}{S\ 8}$   
 1970

Reset the iron pipe alongside the iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, pine, alder, maple, oak, chinquapin, dogwood, madrone, and yew; undergrowth, poison oak, manzanita, fern, blackberry, vine maple, hazel, willow, Oregon grape, salal, arrowwood and wild rose.

S. 80° 30' W., bet. secs. 6 and 7.

Ascend 5 ft. over SE. slope, through heavy timber and moderate undergrowth.

- 0.65 Spur, slopes S.; desc. 185 ft. over SW. slope.
- 5.50 Creek, 2 lks. wide, course S.; asc. 300 ft. over NE. slope.
- 19.15 Spur, slopes SE.; desc. 5 ft. over SW. slope.
- 19.95 Point for the E 1/16 sec. cor. of secs. 6 and 7.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16  $\frac{S\ 6}{S\ 7}$   
 1970

from which

- A pine, 8 ins. diam., bears N. 23½° E., 15 lks. dist., mkd. E 1/16 S6 BT.
- A pine, 54 ins. diam., bears S. 63° E., 58 lks. dist., mkd. E 1/16 S7 BT.

From this point, a point established by John H. Markham, Professional Engineer, No. 2890 in 1952, bears N. 46° E., 10½ lks. dist., monumented with an iron rod, 1 in. diam., firmly set, projecting 5 ins. above ground, from which a tree marked by Markham:

- A pine, 20 ins. diam., bears N. 31° W., 25 lks. dist., with healed blaze.

Descend 5 ft. over SW. slope.

- 20.25 Head of ravine, drains SE.; asc. 270 ft. over SE. slope.
- 24.30 Dirt road, 10 lks. wide, bears NE. and SW.
- 36.85 Spur, slopes S.; desc. 20 ft. over SW. slope, enter open field, edges bear N. and S.
- 39.90 The ¼ sec. cor. of secs. 6 and 7, monumented with the original basalt stone, 14 x 8 x 6 ins., firmly set, 6 ins. in the ground, mkd. ¼ on N. face, alongside of which is an iron pipe, 1 in.