

County Surveyor's Record, Douglas County, Oregon 14522

Dependent Resurvey, Portion of Subdivisional Lines, T. 30 S., R. 2 W.


CHAINS

- 26.30 Swamp, drains SE.; asc. 375 ft. over NE. slope.
- 30.60 Mining ditch, 2 lks. wide, bears N. and S.
- 43.16 The cor. of secs. 1, 6, 7 and 12, on the W. bdy. of the Tp.
Land, mountainous.
Soil, rocky clay.
Timber, fir, cedar, hemlock, pine, alder, madrone and maple;
undergrowth, poison oak, manzanita, fern, blackberry, vine maple,
hazel, willow, Oregon grape, salal, arrowwood and wild rose.

Subdivision of Section 7, T. 30 S., R. 2 W.,
Willamette Meridian, Oregon

From the $\frac{1}{4}$ sec. cor. of sec. 7 only, on the S. bdy. of sec. 7.
North, on the N. and S. center line of sec. 7.
Descend 170 ft. over NW. slope, through moderate timber and
dense undergrowth.

- 8.95 Granite Creek, 10 lks. wide, course SW.; asc. 90 ft. over
SE. slope.
- 13.40 Gravelled road, 15 lks. wide, bears NE. and SW.
- 14.40 Corner of fences, extends N. and SW.; enter along E. edge of a
cultivated field.
- 20.01 Point for the center S 1/16 sec. cor. of sec. 7.
Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the
ground, with brass cap mkd.



from which

- A pine, 10 ins. diam., bears S. 46° E., 60 lks. dist.,
mkd. CS 1/16 S7 BT.
- A pine, 10 ins. diam., bears N. 14° W., 140 lks. dist.,
mkd. CS 1/16 S7 BT.

The cor. is located in a fence line extending N. and S.
Ascend 25 ft. over SE. slope.

- 21.10 Corner of fences extends S. and W.; enter moderate timber
and undergrowth.
- 24.90 Ravine, drains SE.; asc. 205 ft. over SE. slope.
- 36.20 Spur, slopes S. 15° W.; desc. 5 ft. over NW. slope.
- 39.95 Dirt road, 10 lks. wide, bears SE. and NW.; also bottom
of desc., slopes W.; asc. over a slight SW. slope.
- 40.02 Point for the center $\frac{1}{4}$ sec. cor. of sec. 7, at intersection