

14531 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 31 S., R. 2 W.

CHAINS

with brass cap mkd.

N 1/16
S 22 | S 23
1971

from which

A madrone, 10 ins. diam., bears S. 33° E., 15 lks. dist.,
mkd. N 1/16 S23 BT.

A fir, 8 ins. diam., bears S. 54° W., 81 lks. dist., mkd.
N 1/16 S22 BT.

Descend 200 ft. over NW. slope.

61.10 Jeep trail, 10 lks. wide, bears NE. and SW.

81.24 The cor. of secs. 14, 15, 22, and 23, perpetuated by John H. Markham, Registered Engineer, in 1952, subsequently remonumented in 1966 by John M. Powell, Deputy County Surveyor, with an iron pipe, 1½ ins. diam., firmly set protruding 10 ins. above ground with brass cap mkd.

County Surveyors
T 31 S | R 2 W
S 15 | S 14
S 22 | S 23
1966
Office

from which the remaining original bearing tree

A rotted fir stump, 15 ins. diam., bears S. 75° W.,
6 lks. dist., with no marks remaining.

and a bearing tree mkd. by Markham

A cedar snag, 11 ins. diam., bears N. 42° E., 60 lks. dist.,
with scribe marks S14 visible on partly healed blaze.

and bearing trees mkd. by Powell

A cedar, 14 ins. diam., bears N. 2° W., 42 lks. dist., with
scribe marks T31S R2W S15 CS BT visible on partly
healed blaze.

A cedar, 16 ins. diam., bears S. 31° W., 90 lks. dist.,
with scribe marks T31S R2W S22 CS BT visible on partly
healed blaze.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, madrone, pine, cedar, and hemlock; undergrowth, salal,
manzanita, poison oak, willow, and vine maple.

From the ¼ sec. cor. of secs. 11 and 14, remonumented in 1966 by John M. Powell, Deputy County Surveyor, with an iron pipe, 1 in. diam., firmly set, protruding 8 ins. above ground, and in a small mound of stone, with brass cap mkd.

T 31 S
¼ S 11
S 14
R 2 W
1966

from which the remaining original bearing tree