

Dependent Resurvey, Subdivisional Lines, T. 31 S., R. 2 W.

CHAINS

GENERAL DESCRIPTION

The lines included in the foregoing resurvey are situated about 1 mile west of the hamlet of Drew, in Douglas County, Oregon. Access is by way of State Highway No. 227 and two private logging roads branching off from it.

The land is hilly to mountainous, with elevations ranging from about 1,325 ft. above sea level at Elk Creek to about 2,650 ft. above sea level at the corner of secs. 22 and 23 only. The area is situated mostly to the southwest of Elk Creek, into which the entire area is drained.

Soil is composed chiefly of rocky clay loam. Timber consists of fir, cedar, hemlock, pine, madrone, and alder; with undergrowth of vine maple, manzanita, willow, blackberry, and poison oak.

No evidence of mineral deposits were noted on the lines surveyed.

The average of a considerable number of readings throughout the area gives a value of 20° 00' E. for the mean magnetic declination, with a range of 2° in local attraction.