

# County Surveyor's Record, Douglas County, Oregon

14540

Dependent Resurvey, Line Between Sections 13 and 14, T. 23 S., R. 4 W.

CHAINS

- 51.05 Dirt Road, 25 lks. wide, bears N. 70° E., and S. 70° W.
- 59.97 Point for the N 1/16 sec. cor. of secs. 13 and 14.  
Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.  

N 1/16  
S 14 | S 13  
1971

from which  
  - A fir, 7 ins. diam., bears N. 84° E., 15 lks. dist., mkd. N 1/16 S13 BT.
  - A fir, 7 ins. diam., bears N. 59° W., 18½ lks. dist., mkd. N 1/16 S14 BT.Descend 90 ft. over broken N. slope.
- 63.05 Creek, 5 lks. wide, course W.; asc. 110 ft. over SW. slope.
- 75.65 Top of ascent, slopes N.; desc. 40 ft. over N. slope.
- 76.00 3 strand power line, bears N. 75° E., and S. 75° W.
- 76.25 Dirt road, 20 lks. wide, bears N. 82° E., and S. 82° W.
- 79.96 The cor. of secs. 11, 12, 13, and 14, perpetuated and recorded by Wilford N. Haines, Registered Land Surveyor No. 239, in 1963, monumented with a 1 in. T iron, firmly set, projecting 10 ins. above ground, from which the remaining original bearing tree:  
  - A decayed fir stump, size indeterminate, bears N. 27° W., 295 lks. dist.; no marks remaining.and bearing trees mkd. by Haines  
  - A fir, 15 ins. diam., bears N. 23¼° E., 153 lks. dist., with healed blaze.
  - A cedar, 18 ins. diam., bears S. 9½° E., 135 lks. dist., with fragmentary scribe marks visible on partially healed blaze.
  - A fir, 13 ins. diam., bears S. 58¼° W., 87½ lks. dist., with healed blaze.
  - A fir, 20 ins. diam., bears N. 23 3/4° W., 114 lks. dist., with scribe marks S11 T23S R4W BT visible on bark blaze.At the corner point  
Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground directly atop the T iron, with brass cap mkd.  

T 22 S R 4 W  
S 11 | S 12  
S 14 | S 13  
1971

from which new bearing trees  
  - A fir, 6 ins. diam., bears N. 68½° E., 18 lks. dist., mkd. T23S R4W S12 BT.

*FD OK  
11-12-97  
Roberts M127-75*