

County Surveyor's Record, Douglas County, Oregon

14552

Dependent Resurvey, East Boundary, T. 23 S., R. 10 W.

CHAINS

- 35.95 Ravine, drains N. 55° E.; desc. 5 ft. over N. slope.
 - 39.03 The closing corner of Tps. 23S., Rs. 9 and 10 W., hereinbefore described.
- From this point the $\frac{1}{4}$ sec. cor. of secs. 6 and 31, bears N. 89° 22' E., 12.105 chs. dist., hereinbefore described.
- Land, mountainous.
Soil, clay loam.
Timber, fir, hemlock, cedar, oak, maple, alder, and dogwood;
undergrowth, arrowwood, salal, Oregon Grape, poison oak,
and fern.

Dependent Resurvey of a Portion of the
Subdivisional Lines, T. 23 S., R. 9 W.
Willamette Meridian, Oregon

(Restoring the 1879 survey by William H. Byars,
and the 1898-99 survey by Oscar F. Thiel)

Beginning at the cor. of secs. 13, 14, 23, and 24, determined at record bearing and distance from the remaining original bearing trees:

- A maple snag, 30 ins. diam., bears N. 12° E., 47 lks. dist., no marks visible.
- A maple, 16 ins. diam., bears S. 7° E., 25 lks. dist., no marks visible on opened blaze.
- A hemlock stump, 36 ins. diam., bears S. 5° W., 102 lks. dist., no marks visible.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 23 S R 9 W
S 14 | S 13
S 23 | S 24
1969

from which new bearing trees

- A hemlock, 28 ins. diam., bears N. 12° E., 105 lks. dist., mkd. T23S R9W S13 BT.
- A hemlock, 13 ins. diam., bears S. 50° W., 60 lks. dist., mkd. T23S R9W S23 BT.
- A fir, 23 ins. diam., bears N. 24° W., 16 lks. dist., mkd. T23S R9W S14 BT.

S 89° 24' E., bet. secs. 13 and 24, marking and blazing the true line.

Descend 150 ft. over E. slope.