

County Surveyor's Record, Douglas County, Oregon

14554

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 9 W.

CHAINS	
	<p>T 23 S R 9 W N$\frac{1}{4}$ sec. 24 established 6-6-66 George C. Barton Crystal M. Barton</p> <hr style="width: 30%; margin: auto;"/>
	<p>S. 88° 30' E., beginning new measurement.</p> <p>Descend 20 ft. over broken S. slope.</p>
3.35	<p>Creek, 2 lks. wide, course S. 55° W.; asc. 330 ft. over general W. slope.</p>
19.62	<p>Point for the E 1/16 sec. cor. of secs. 13 and 24.</p> <p>Set an iron post, 28 ins. long, 2$\frac{1}{2}$ ins. diam., 24 ins. in ground, with brass cap mkd.</p> <p style="text-align: center;"> E 1/16 $\frac{S\ 13}{S\ 24}$ 1969 </p> <p>from which</p> <p style="padding-left: 40px;">A fir, 20 ins. diam, bears N. 14° E., 32 lks. dist., mkd. E 1/16 S13 BT.</p> <p style="padding-left: 40px;">A cedar, 35 ins. diam., bears S. 31 3/4° E., 87$\frac{1}{2}$ lks. dist., mkd. E 1/16 S24 BT.</p> <p>Ascend 300 ft. over SW. slope.</p>
30.10	<p>Spur, slopes S. 30° W.; desc. 60 ft. over SE. slope.</p>
37.92	<p>The closing cor. of secs. 13 and 24, hereinbefore described.</p> <p>From this point, the cor. of secs. 18 and 19 only, T. 23 S., R. 8 W., bears N. 0° 24' E., 20.05 chs. distant, hereinbefore described.</p> <p>Land, mountainous. Soil, rocky clay loam. Timber, fir, hemlock, cedar, maple, chinquapin, alder, and myrtle; undergrowth, salal, hazel, rhododendron, Oregon Grap, huckleberry, blackberry, arrowwood and fern.</p>
	<p>From the cor. of secs. 13, 14, 23 and 24.</p> <p>N. 0° 16' W., bet. secs. 13 and 14.</p> <p>Ascend 5 ft. over nearly level land, through scattering timber and moderate undergrowth.</p>
1.40	<p>Top of ascent, slopes E.; desc. 20 ft. along E. slope.</p>
5.40	<p>Creek, 1 lk. wide, course S. 50° E.; asc. 220 ft. over S. slope.</p>
14.80	<p>Spur, slopes S. 60° E.; desc. 175 ft. ove N. slope.</p>
18.45	<p>Ravine, drains N. 40° E.; asc. slightly over SE. slope.</p>
19.705	<p>Point for the S 1/16 sec. cor. of secs. 13 and 14.</p>