

County Surveyor's Record, Douglas County, Oregon

14556

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 9 W.

CHAINS

- 23.05 Spur, slopes S. 75° E.; desc. 30 ft. over NE. slope.
- 25.05 Bottom of descent, slopes E.; asc. 50 ft. over SW. slope.
- 28.70 Spur, slopes N. 40° E.; desc. 125 ft. over NW. slope.
- 34.95 Spur, slopes N. 35° W.; desc. 175 ft. over N. slope.
- 38.20 Creek, 3 lks. wide, course N. 75° E.; asc. 210 ft. over SE. slope.
- 48.90 Spur, slopes S. 60° E.; desc. 55 ft. over NE. slope.
- 51.80 Ravine, drains S. 60° E.; asc. 295 ft. over S. slope.
- 61.30 Enter old logged area, edge bears generally N. and S.
- 62.30 Gravelled road, 50 lks. wide, bears N. 75° W. and S. 70° E.
- 70.95 Spur ridge, bears E. and W.; desc. 185 ft. over N. slope.
- 74.98 The cor. of secs. 11, 12, 13, and 14, determined at record distance from the original bearing trees:

A root hole, bears N. 54° E., 100 lks. dist., with a down fir alongside, 30 ins. diam., no marks visible. (Record, N. 60° E.)

A maple, 36 ins. diam., bears S. 77° E., 60 lks. dist., with healed blaze. (Record, S. 71° E.)

A sawed fir stump, 40 ins. diam., bears S. 54° W., 27 lks. dist., no marks remaining. (Record, S. 60° W.)

A sawed fir stump, 70 ins. diam., bears N. 19° W., 30 lks. dist., no marks remaining. (Record, N. 12° W.)

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in ground, with brass cap mkd.

FD
OK
M. Smalley
10/97
M124-64

T 23 S R 9 W			
S 11		S 12	
S 14		S 13	
1969			

from which new bearing trees

A hemlock, 25 ins. diam., bears N. 34° E., 101 lks. dist., mkd. T23S R9W S12 BT.

A maple, 15 ins. diam., bears S. 89° W., 51 lks. dist., mkd. T23S R9W S14 BT.

A hemlock, 8 ins. diam., bears N. 44° W., 95 lks. dist., mkd. T23S R9W S11 BT.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, maple, chinquapin, alder, and myrtle; undergrowth, rhododendron, salal, hazel, Oregon Grape, arrowwood and fern.