

# County Surveyor's Record, Douglas County, Oregon

14559

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 9 W.

CHAINS

from which new bearing trees

A fir, 26 ins. diam., bears S. 51° E., 210 lks. dist.,  
mkd.  $\frac{1}{4}$  S20 BT.

A fir, 19 ins. diam., bears S. 11° W., 235 lks. dist.,  
mkd.  $\frac{1}{4}$  S19 BT.

N. 1° 14' E., bet. secs. 19 and 20.

Ascend gradual S. slope, across open field.

8.40 Enter scattering timber and moderate undergrowth, edge bears E. and W.; ascend 220 ft. over S. slope.

13.45 Dirt road, 20 lks. wide, bears N. 60° E. and S. 80° W.

19.92 Point for the N 1/16 sec. cor. of secs. 19 and 20.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in ground, with brass cap mkd.

N 1/16  
S 19 | S 20  
1969

from which

A fir, 15 ins. diam., bears S. 86° E., 130 lks. dist.,  
mkd. N 1/16 S20 BT.

A fir, 15 ins. diam., bears N. 45½° W., 33½ lks. dist.,  
mkd. N 1/16 S19 BT.

Ascend 5 ft. over S. slope.

20.80 Spur, slopes SW.; desc. 195 ft. over NW. slope.

35.20 Bottom of descent, slopes W.; asc. 35 ft. over SW. slope.

37.35 Spur, slopes W.; desc. 50 ft. over NW. slope.

38.50 Gravelled road, 30 lks. wide, bears N. 40° E. and S. 50° W.

39.84 Point for the cor. of secs. 17, 18, 19 and 20 at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in ground, with brass cap mkd.

T 23 S R 9 W  
S 18 | S 17  
S 19 | S 20  
1969

from which

An alder, 7 ins. diam., bears N. 17° E., 37½ lks. dist.,  
mkd. T23S R9W S17 BT on bark blaze.

An alder, 9 ins. diam., bears S. 64½° E., 40 lks. dist.,  
mkd. T23S R9W S20 BT on bark blaze.

An alder, 6 ins. diam., bears S. 23° W., 41 lks. dist.,  
mkd. T23S R9W S19 BT on bark blaze.

An alder, 7 ins. diam., bears N. 74 ¾° W., 40½ lks. dist.,  
mkd. T23S R9W S18 BT on bark blaze.