

# County Surveyor's Record, Douglas County, Oregon

14561

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S. R. 9 W.

CHAINS

A sawed fir stump, 50 ins. diam., bears N. 50° E., 48 lks. dist., with scribe marks T23S R9W S16 BT visible on opened blaze.

A rotted fir snag, 45 ins. diam., bears N. 64° W., 69 lks. dist., no marks visible.

and a locally established bearing tree

A Hemlock, 17 ins. diam., bears S. 66° W., 32 lks. dist., with healed blaze.

35.40 Ravine, drains S. 50° E.; asc. 65 ft. over E. slope.

37.35 The  $\frac{1}{4}$  sec. cor. of secs. 17 and 20, determined at record bearing and distance from the original bearing trees:

A root hole, bears N. 35° W., 25 lks. dist., with a down fir alongside, 47 ins. diam., with fragmentary scribe marks visible on bark.

A burned fir snag, 24 ins. diam., bears S. 80° E., 10 lks. dist., no marks visible.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in ground, with brass cap mkd.

T 23 S R 9 W  
 $\frac{1}{4}$  S 17  
 S 20  
 1969

from which

A hemlock, 15 ins. diam., bears N. 66° E., 18 lks. dist., mkd.  $\frac{1}{4}$  S17 BT.

A fir, 6 ins. diam., bears S. 16° W., 34 lks. dist., mkd.  $\frac{1}{4}$  S20 BT.

---

S. 89° 31' W., beginning new measurement.

Ascend 165 ft. over SE. slope.

8.70 Spur, slopes S. 40° W.; desc. 400 ft. over W. slope.

22.80 Head of ravine, drains N. 30° W.; asc. 40 ft. over NE. slope.

24.90 Spur, slopes N. 40° W.; desc. 35 ft. over NW. slope.

25.95 Ravine, drains N. 40° W.; asc. 10 ft. over NE. slope.

26.75 Spur, slopes N. 50° W.; desc. 220 ft. over NW. slope.

39.20 Gravelled road, 30 lks. wide, bears N. 10° W. and S.

39.35 Board and wire fence, bears N. 10° W. and S.

40.61 The cor. of secs. 17, 18, 19, and 20.

Land, mountainous.  
 Soil, rocky clay loam  
 Timber, fir, hemlock, alder, maple, cedar, chinquapin, and myrtle;  
 undergrowth, salal, hazel, huckleberry, Oregon Grape, salmonberry,  
 arrowwood and fern.