

# County Surveyor's Record, Douglas County, Oregon

14562

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S. R. 9 W.

CHAINS

N. 89° 19' W., bet. secs. 18 and 19.

Descend 5 ft. over nearly level land.

0.50 Creek, 5 lks. wide, course S. 10° W.; asc. slightly over nearly level land.

5.00 Barbed wire fence; bears NE. and SW.

8.75 Creek, 5lks. wide, course S. 20° W.; asc. 240 ft. over SE. slope.

20.23 Point for the E 1/16 sec. cor. of secs. 18 and 19.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in ground, with brass cap mkd.

E 1/16  $\frac{S\ 18}{S\ 19}$   
1969

from which

A fir, 9 ins. diam., bears N. 38 3/4° E., 41 lks. dist., mkd. E 1/16 S18 BT.

A fir, 7 ins. diam., bears S. 16° W., 26 lks. dist., mkd. E 1/16 S19 BT.

Ascend 85 ft. over SE. slope.

23.90 Spur, slopes S. 5° E.; desc. 135 ft. over SW. slope.

28.35 Ravine, drains S. 30° E.; asc. 155 ft. over E. slope.

33.10 Spur, slopes S. 30° E.; desc. 85 ft. over SW. slope.

40.46 The ¼ sec. cor. of secs. 18 and 19, monumented with a wooden post, 2 ins. square, firmly set, projecting 36 ins. above ground, from which the original bearing trees:

A sawed fir stump, 45 ins. diam., bears N. 20° E., 42 lks. dist., no marks visible on rotted face.

A sawed fir stump, 45 ins. diam., bears S. 64° E., 25 lks. dist., no marks visible. (Record, S. 70° E.)

At the corner point

Set an iron post, 28 ins. long 2½ ins. diam., 24 ins. in ground, with brass cap mkd.

T 23 S R 9 W  
¼  $\frac{S\ 18}{S\ 19}$   
1969

from which

A fir, 10 ins. diam., bears N. 9½° W., 26 lks. dist., mkd. ¼ S18 BT.

A fir, 9 ins. diam., bears S. 17° E., 28 lks. dist., mkd. ¼ S19 BT.