

# County Surveyor's Record, Douglas County, Oregon

11572

Dependent Resurvey, Portion of Subdivisional Lines, T. 27 S., R. 1 W.

CHAINS

T 27 S R 1 W  
 W C  
 $\frac{1}{4}$   
 S 2  $\uparrow$  S 1  
 1971

from which a new bearing tree

A fir, 8 ins. diam., bears N. 87° W., 58 lks. dist.,  
 mkd. X BT.

N. 0° 40' W., beginning new measurement.

- 0.30 Edge of marsh, bears N. 45° E. and S. 45° W.; continue through marsh and dense undergrowth.
- 6.96 Point for the  $\frac{1}{4}$  sec. cor. of secs. 1 and 2, at proportionate dist., falls in swamp where it is impracticable to establish a permanent monument.
- 13.50 Leave marsh, enter clear cut logged area, edge bears NW. and SE.; asc. 125 ft. over S. slope.
- 19.60 Gravelled road, 20 lks. wide, bears N. 70° W. and S. 70° E.
- 28.50 Spur, slopes E.; desc. 260 ft. over NE. slope.
- 41.40 Cougar Creek Road, 30 lks. wide, bears N. 70° W. and S. 70° E.
- 46.35 The cor. of secs. 1 and 2 only, on the N. bdy. of the Tp., perpetuated by Thomas E. Shrum, Jr., Registered Engineer No. 4287, with an iron pipe, 1 in. diam., firmly set, protruding 16 ins. above the ground, with aluminum cap mkd.

U.S.P.C.  
35  
 2 | 1  
 PROP. COR.  
 RE. 4287

from which the remains of the original bearing tree

A root hole, bears S. 61° E., 54 lks. dist., alongside of which is lying a fir, 24 ins. diam., with scribe marks 27S 1W S1 visible on partially healed blaze.

and a bearing tree tagged by RE. 4287

A hemlock, 20 ins. diam., bears S. 53° E., 79 lks. dist., with metal tag attached, mkd. S1 BT.

and a bearing tree marked by Douglas County Surveyor, in 1969

A hemlock, 16 ins. diam., bears S. 43° E., 93 lks. dist., scribed T27S R1W S1 CS BT on a partially healed blaze.

Add the marks HLM 1971 to aluminum cap.

Suspension Lifted 10/30/1981