

County Surveyor's Record, Douglas County, Oregon

14508

Dependent Resurvey, Portion of Subdivisional Lines, T. 27 S., R. 1 W.

CHAINS

W C
S 1/16
↑
S 8 | S 9
1971

from which

A fir, 5 ins. diam., bears S. 57° E., 7 lks. dist.,
mkd. X BT.

A fir, 5 ins. diam., bears S. 40° W., 41 lks. dist., mkd.
X BT.

19.95 True point for the S 1/16 sec. cor. of secs. 8 and 9, falls in Little Taft Creek, 5 lks. wide, course S. 80° W., where it is impracticable to establish a permanent monument.

Ascend 465 ft. over SW. slope.

26.35 Spur, slopes SW.; continue ascent along SW. slope.

39.90 The 1/4 sec. cor. of secs. 8 and 9, monumented with the original basalt stone, 11 x 10 x 6 ins., firmly set, 10 ins. in the ground with fragmentary chisel marks visible on W. face, from which the original bearing trees:

A fir, 17 ins. diam., bears N. 4 1/2° E., 30 lks. dist., mkd. with healed blaze and old metal location tag. (Record, N. 33° E., 29 lks.)

A cedar, 18 ins. diam., bears S. 4° W., 60 lks. dist., with fragmentary scribe marks visible on partially healed blaze. (Record, S. 32 1/2° W., 58 lks.)

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 27 S R 1 W
1/4
S 8 | S 9
1971

Deposit original stone alongside iron post.

Land, mountainous.

Soil, rocky clay and loam.

Timber, fir, pine and hemlock; undergrowth, vine maple, salal, and huckleberry.

From the cor. of secs. 17, 18, 19, and 20, remonumented by the Douglas County Surveyor, in 1969, from a perpetuation of which I have no record, with an iron pipe, 1 1/2 ins. diam., protruding 16 ins. above ground, with brass cap mkd.

T 27 S R 1 W
S 18 | S 17
S 19 | S 20
BLM 1971
1969

from which

A fir, 6 ins. diam., bears S. 81° E., 47 lks. dist., with scribe marks S20 CS BT visible on partially healed blaze.

Suspension lifted 10/30/1981