

County Surveyor's Record, Douglas County, Oregon

145.8

Dependent Resurvey, Portion of Subdivisional Lines, T. 27 S., R. 1 W.

CHAINS

COUNTY SURVEYORS OFFICE

T 27 S
R | S 18 R
2 | S 19 1
W | W
1968

from which the remaining original bearing tree

A hemlock stump, 24 ins. diam., bears S. 26° E., 13 lks. dist., with scribe mark B visible on badly rotted face.

and a bearing tree marked by the County Surveyor

A fir stump, 40 ins. diam., bears N. 34° E., 90 lks. dist., no marks visible on burned and rotted blaze.

A 1/2 in. steel re-bar and a steel fence post, 6 ft. long, deposited alongside the iron pipe.

Add the marks HLM 1971 to the brass cap.

Land, mountainous.

Soil, clay and loam.

Timber, fir, pine and hemlock reproduction; undergrowth, salal, Oregon grape, willow and vine maple.

From the cor. of secs. 8, 9, 16, and 17.

N. 89° 24' W., bet. secs. 8 and 17.

Descend 20 ft. over SW. slope, through scattered timber and dense undergrowth.

0.85 Creek, 2 lks wide, course N. 45° W.; asc. 65 ft. over broken N. slope.

4.80 Slope change; desc. 325 ft. over generally NW. slope.

19.915 True point for the E 1/16 sec. cor. of secs. 8 and 17; falls in Little Taft Creek, 7 lks. wide, course S. 30° W., where it is impracticable to establish a permanent monument.

20.31 Point selected for the witness cor. to the E 1/16 sec. cor. of secs. 8 and 17.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 6 ins. in the ground, to solid rock, and in a mound of stone, 4 ft. base to top, with brass cap mkd.

W C
E 1/16 ——— S 8 —→
S 17
1971

from which

A fir, 6 ins. diam., bears N. 74° E., 119 lks. dist., mkd. X BT.

No suitable bearing trees available to the S.

Ascend 85 ft. over SE. slope.

Suspension lifted 10/30/1981