

Dependent Resurvey, Portion of S. Bdy., T. 29 S., R. 1 W.

CHAINS

from which the remaining original 1857 bearing tree, recovered and reblazed by F. Mensch

A fir stump, 35 ins. diam., bears N. 61° W., 38 lks dist., mkd. with healed blaze.

and bearing tree mkd. by F. Mensch

A down and rotted fir, 14 ins. diam., bears S. 38° E., 49 lks. dist., mkd. with a rotted face.

and bearing trees mkd. by J. H. Markham

A fir, 12 ins. diam., bears S. 10° W., 29 lks. dist., scribe marks S6 RLW visible on partly healed blaze.

An oak, 10 ins. diam., bears N. 87° W., 14 lks. dist., scribe marks S31 RLW visible on partly healed blaze.

Cor. falls in a logged area, overgrown with undergrowth and reproduction.

S. 89° 46' W., bet. secs. 6 and 31.

Ascend 153 ft. over broken E. slope, through a logged area and dense undergrowth.

3.30 Creek, 4 lks. wide, course S. 82° E.

20.325 Point for the E 1/16 sec. cor. of secs. 6 and 31.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

E 1/16    S 31  
                  S 6  
1971

from which

A fir, 10 ins. diam., bears N. 7° E., 29 lks. dist., mkd. E 1/16 31 BT.

A fir, 9 ins. diam., bears S. 9½° W., 37 lks. dist., mkd. E 1/16 S6 BT.

Ascend 103 ft. over broken E. slope.

40.65 The ¼ sec. cor. of secs. 6 and 31, perpetuated and recorded by John H. Markham, Registered Engineer, in 1960, subsequently re-monumented by J. A. Hoffbuhr, Registered Land Surveyor No. 222, in 1970, with an iron post, 2½ ins. diam., firmly set, extending 12 ins. above ground, with brass cap mkd.

T 29 S    R 1 W  
¼        S 31  
                  S 6  
T 30 S    R 1 W  
                  RLS 222  
                  1970