

County Surveyor's Record, Douglas County, Oregon

11591

Dependent Resurvey, Portion of Subdivisional Lines, T. 27 S., R. 2 W.

CHAINS

and trees marked by Tracy, in 1968

A fir, 10 ins. diam., bears N. 88° E., 21 lks. dist.,
with healed blaze.

A fir, 7 ins. diam., bears N. 40° W., 30 lks. dist., with
scribe marks T27S R2W S5 CS BT visible on partially
healed blaze.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, cedar, maple, madrone, pine, and alder; undergrowth,
vine maple, salal, fern hazel, and poison oak.

From the cor. of secs. 8 and 9 only, on the N. bdy. of sec. 17,
monumented with the original basalt stone, 15 x 7 x 6 ins., firmly
set 10 ins. in the ground, marked with 4 notches on S. and 4 notches
on E. edge, from which the original bearing trees

A fir, 44 ins. diam., bears N. 81° E., 69 lks. dist.,
with healed blaze.

A madrone, 20 ins. diam., bears S. 31° E., 47 lks. dist.,
with healed blaze.

A fir, 42 ins. diam., bears S. 56° W., 15 lks. dist., with
healed blaze.

A fir, 43 ins. diam., bears N. 19° W., 69 lks. dist.,
with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins. in the
ground, with brass cap marked

$$\begin{array}{c} \text{S } 8 \text{ S } 9 \\ \text{S } 17 \\ \text{T27S R2W} \\ 1971 \end{array}$$

Deposit original stone alongside the iron post.

N. 0° 15' W., bet. secs. 8 and 9.

Ascend 130 ft. over SE. slope, through heavy timber and dense
undergrowth.

5.70 Spur, slopes N. 70° E.; descend 520 ft. over NE. slope.

20.14 Point for the S. 1/16 sec. cor. of secs. 8 and 9.

Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins. in the
ground, with brass cap marked

$$\begin{array}{c} \text{S } 1/16 \\ \text{S } 8 \text{ S } 9 \\ 1971 \end{array}$$

from which