

# County Surveyor's Record, Douglas County, Oregon

14587

Dependent Resurvey, Portion of Subdivisional Lines, T. 27 S., R. 2 W.

CHAINS

At the corner point

Set a brass tablet,  $3\frac{1}{2}$  ins. diam., 3 in. stem. in drill hole, in solid rock, with top mkd.

T27S R2W  
 $\frac{S}{S} \frac{6}{7} | \frac{S}{S} \frac{5}{8}$   
 1971

Land, mountainous.  
 Soil, rocky clay loam.  
 Timber; fir, cedar, hemlock, maple, madrone, alder, and chinquapin; undergrowth, vine maple, salal, hazel, fern, ceanothus, and poison oak.

From the cor. of sec. 4 and 5 only, on the N. bdy. of sec. 8.

N.  $89^{\circ} 49'$  W., along the S. bdy. of sec. 5.

Ascend 155 ft. over SE. slope, through heavy timber and moderate undergrowth.

18.85 Spur, slopes S.  $5^{\circ}$  W.; desc. 270 ft. over SW. slope.

Descend 5 ft. over SW. slope.

39.26 Point for the  $\frac{1}{4}$  sec. cor. of sec. 8 only, hereinafter described.

39.63 Point for the  $\frac{1}{4}$  sec. cor. of sec. 5 only, determined by the method of irregular boundaries; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap marked

$\frac{1}{4}$  S 5  
 -----  
 T27S R2W  
 1971

from which

A fir, 55 ins. diam., bears N.  $81^{\circ}$  W., 89 lks. dist., marked  $\frac{1}{4}$  S5 BT.

No other suitable trees available within limits.

N.  $89^{\circ} 56'$  W., beginning new measurement.

Descend 100 ft. over SW. slope.

2.60 Greenman Creek, 10 lks. wide, course S.  $30^{\circ}$  E.; asc. 785 ft. over E. slope.

35.90 Spur, slopes S.  $5^{\circ}$  W.; desc. 40 ft. over SW. slope.

39.94 The cor. of secs. 5, 6, 7, and 8.

Land, mountainous.  
 Soil, rocky clay loam.  
 Timber, fir, hemlock, cedar, maple, alder, madrone, and chinquapin; undergrowth, vine maple, ceanothus, hazel, salal, fern, and poison oak.