

14604 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of E. Bdy., T. 23 S., R. 10 W.

CHAINS

A fir snag, 36 ins. diam., bears S. 25° E., 25 lks. dist., no marks remaining. (Record, S. 30° E., 36 lks.)

A sawed fir stump, 36 ins. diam., bears S. 33° W., 56 lks. dist., no marks remaining. (Record, S. 30° W., 53 lks.)

A rotted fir stump, size indeterminate, bears N. 45° W., 2 lks. dist., no marks remaining.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 21 ins. in the ground, with brass cap mkd.

T 23 S
R 10 W R 9 W
S 12 | S 7
S 13 | S 18
1967

from which

A hemlock, 12 ins. diam., bears N. 15° E., 53 lks. dist., mkd. T23S R9W S7 BT.

A hemlock, 14 ins. diam., bears S 9° E., 28 lks. dist., mkd. T23S R9W S18 BT.

A hemlock, 11 ins. diam., bears S. 42° W., 41½ lks. dist., mkd. T23S R10W S13 BT.

A hemlock, 15 ins. diam., bears N. 11° W., 45 lks. dist., mkd. T23S R10 W S12 BT.

Land, south half mile, bottom land in Ash Valley, north half mile mountainous.

Soil, loam, rocky clay.

Timber, fir, hemlock, cedar, alder, myrtle, dogwood and maple; undergrowth, blackberry, salal, hazel, poison oak, arrowwood, vines and ferns.

Dependent Resurvey, Portion of the Subdivisional Lines, T. 23 S., R. 10 W., Willamette Meridian, Oregon

(Restoring the 1879 survey by William H. Byars)

From the cor. of secs. 13, 18, 19 and 24, on the E. bdy. of the Tp.

N. 89° 30' W., bet. secs. 13 and 24, marking and blazing the true line.

Ascend slightly across Ash Valley, along barbed wire fence, through thickets of blackberry vines.

16.85 Barbed wire fence, bears N., S., and E.

17.55 Paved road, 30 lks. wide, bears N. 30° W. and S. 10° W.

25.20 Lake Creek, 40 lks. wide, course N. 40° E.; continue across Ash Valley.