

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 29 S., R. 6 W.

CHAINS

visible on open blaze.

A fir stump, 18 ins. diam., bears N. 83° W.,
43 lks. dist., with no marks visible on
opened blaze.

and bearing trees marked by Byron in 1962

A white oak, 10 ins. diam., bears N. 47° E.,
141 lks. dist., with healed blaze.

A fir, 9 ins. diam., bears S. 67° W.,
82 lks. dist., with healed blaze.

A fir snag, 23 ins. diam., bears N. 27° W.,
119 lks. dist., with scribe marks T29S
R6W S15 CS BT visible on opened blaze.

and new bearing trees

A fir, 14 ins. diam., bears S. 25° E.,
248 lks. dist., marked T29S R6W S23 BT.

A cedar, 7 ins. diam., bears N. 35° W.,
77 lks. dist., marked T29S R6W S15 BT.

N. 1° 36' E., bet. secs. 14 and 15.

Descend 45 ft. over N. slope, through scattering timber
and light undergrowth, marking and blazing the true
line.

- 1.05 Dirt road, 15 lks. wide, bears N. 65° W. and S. 65° E.
5.50 Creek, 10 lks. wide, course N. 80° W.; asc. 120 ft. over
S. slope.
14.50 Spur, slopes S. 65° W.; desc. 95 ft. over NW. slope.
20.95 Ravine, drains S. 30° W.; asc. 270 ft. over S. slope.
38.93 The 1/4 sec. cor. of secs. 14 and 15, perpetuated by
F.C. Frear, Deputy County Surveyor, in 1919, when
original corner evidence was existent, further perpetu-
ated by James W. Byron, County Surveyor, in 1962, monu-
mented with an iron post, 1 ins. diam., firmly set, pro-
truding 4 ins. above ground, with brass cap marked

COUNTY SURVEYORS OFFICE

T 29 S R 6 W
1/4 S 15 | S 14
1962

from which a bearing tree marked by Frear in 1919

A fir, 18 ins. diam., bears S. 69° E.,
10 lks. dist., with healed blaze.

and a bearing tree marked by Byron in 1962

A fir, 16 ins. diam., bears S. 27° W.,
64 lks. dist., with healed blaze.

and new bearing trees

A white oak, 9 ins. diam., bears N. 31° E.,
30 lks. dist., marked 1/4 S14 BT.