

County Surveyor's Record, Douglas County, Oregon

14828

Dependent Resurvey, Portion of Subdivisional Lines, T. 33 S. R. 5 W.

CHAINS	
	Ascend 5 ft. along N. slope.
1.60	Spur, slopes N., decs. 80 ft. along N. slope.
14.10	Gravelled road, 15 lks. wide, bears N. 55° E. and S. 55° W.
17.30	Creek, 10 lks wide, course N. 40° E.; asc. 130 ft. over SE. slope.
22.38	Point for the W. 1/16 sec. cor. of secs. 1 and 12. Set and iron post, 28 ins. long, 2-1/2 ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> $\begin{array}{r} \text{W } 1/16 \text{ } \frac{\text{S } 1}{\text{S } 12} \\ 1970 \end{array}$ </div> from which A douglas fir, 8 ins. diam., bears N. 27° E., 30 lks dist., mkd. W 1/16 S1 BT. A douglas fir, 8 ins. diam., bears S. 48° W., 64-1/2 lks. dist., mkd. W 1/16 S12 BT. Ascend 530 ft. over SE. slope along N. edge of logged area.
44.76	The cor. of secs. 1,2,11, and 12, monumented with an iron post, 2-1/2 ins diam., firmly set, protruding 2 ins. above ground, with brass cap mkd. and witnessed as described in the official record of the 1966 remonumentation. Land, mountainous. Soil, rocky clay. Timber, fir, pine, cedar, and madrone; undergrowth, salal, manzanita live oak, willow, poison oak, huckleberry, fern, and reproduction timber.
	N. 0° 13' W., bet. secs. 1 and 2. Ascend 30 ft. over SE. slope, through heavy timber and dense undergrowth, along E. edge of logged area.
3.65	Ridge, bears N. 20° E. and S. 25° W.; desc. 225 ft. over NW. slope.
19.805	Point for the S 1/16 sec. cor. of secs. 1 and 2. Set an iron post, 28 ins. long, 2-1/2 ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> $\begin{array}{r} \text{S } 1/16 \\ \text{S } 2/S 1 \\ 1970 \end{array}$ </div> from which A Ponderosa pine, 21 ins. diam., bears N. 32° E. , 55 lks. dist., mkd. S 1/16 S1 BT. A Douglas fir, 8 ins. diam., bears S. 42-1/2° W., 36 lks. dist., mkd. S1/16 S2 BT. Descend 50 ft. over NW. slope.