

County Surveyor's Record, Douglas County, Oregon

14844

Dependent Resurvey, Portion of Subdivisional Lines, T. 22 S., R. 10 W.

CHAINS

Dependent Resurvey of a Portion
of the Subdivisional Lines,
T. 22 S., R. 10 W., Willamette Meridian, Oregon

(Restoring the 1878 survey by William H. Byars,
and the 1894 survey by Aurelius Todd)

From the cor. of secs. 35 and 36 only, on the S bdy. of the Tp.

N. 0° 48' E., bet. secs. 35 and 36, marking and blazing the true line.

Descend 190 ft. over N. slope, through scattering timber and dense undergrowth.

4.20 Mill Creek, 60 lks. wide, course W.; asc. 565 ft. over broken S. slope.

7.10 Paved road, 30 lks. wide, bears E. and W.

19.945 Point for the S 1/16 sec. cor. of secs. 35 and 36.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

S 1/16
S 35 | S 36
1970

from which

A hemlock, 23 ins. diam., bears S. 55° E., 32 lks. dist., mkd. S 1/16 S 36 BT.

A hemlock, 15 ins. diam., bears N. 47° W., 45 lks. dist., mkd. S 1/16 S 35 BT.

Ascend 25 ft. over SE. slope.

24.65 Top of ascent, slopes E.; desc. 485 ft. over broken NE. slope.

39.89 Point for the 1/4 sec. cor. of secs. 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

1/4
S 35 | S 36
T 22 S R 10 W
1970

from which

A fir, 10 ins. diam., bears S. 82 3/4° E., 92 lks. dist., mkd. 1/4 S36 BT.

A fir, 5 ins. diam., bears N. 17 1/2° W., 68 1/2 lks. dist., mkd. 1/4 S35 BT.

Descend 40 ft. over NE. slope.

43.25 Bottom of descent, slopes E.; desc. 390 ft. over broken SE. slope.