

County Surveyor's Record, Douglas County, Oregon

14816

Dependent Resurvey, Portion of Subdivisional Lines, T. 22 S., R. 10 W.

CHAINS	
	<p style="text-align: center;">A sandstone boulder, 7 x 7 x 6 ft. high, bears N. 34 1/4° W., 30 lks. dist., mkd. X B O.</p> <p>There are no suitable trees available within limits.</p> <p>N. 89° 57' W., bet. secs. 25 and 36.</p> <p>Ascend 95 ft. over SE. slope, through heavy timber and dense undergrowth.</p>
4.75	Spur, slopes S.; desc. 175 ft. over SW. slope.
9.75	Paved road, 30 lks. wide, bears N. 45° W. and S. 45° E.
10.45	Camp Creek, 10 lks. wide, course N. 45° W.; asc. 120 ft. over broken NE. slope.
19.25	Point of rocky spur, slopes N.; desc. 15 ft. over NW. slope.
20.485	Point for the W 1/16 sec. cor. of Sec. 25 only.
	<p>Set a brass tablet, 3 1/4 ins. diam., d 1/2 ins. stem, in drill hole, in solid rock, with top mkd.</p> <p style="text-align: center;"><u>W 1/16 S 25</u> 1970</p> <p>from which</p> <p style="text-align: center;">A fir, 10 ins. diam., bears N. 7° E., 45 lks. dist., mkd. X.</p> <p style="text-align: center;">A fir, 10 ins. diam., bears N. 45 3/4° E., 27 1/2 lks. dist., mkd. W 1/16 S25 BT.</p> <p>Descend 130 ft. over rocky W. slope.</p>
22.85	Camp Creek, 10 lks. wide, course S.; asc. 330 ft. over E. slope.
23.85	Same paved road, 30 lks. wide, bears N. and S.
40.97	The cor. of secs. 25, 26, 35, and 36.
	<p>Land, mountainous. Soil, rocky clay loam. Timber, fir, hemlock, cedar, oak, maple, and dogwood; undergrowth, salal, hazel, poison oak, Oregon grape and vine maple.</p>
	<p>N. 3° 22' W., bet. secs. 25 and 26.</p> <p>Ascend 570 ft. over broken S. slope.</p>
17.35	Dirt road, 10 lks. wide, bears N. 60° E. and S. 60° W.
19.43	Point for the S 1/16 sec. cor. of secs. 25 and 26.
	<p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 1/16 S 26 S 25 T 22 S R 10 W 1970</p> <p>from which</p>