

# County Surveyor's Record, Douglas County, Oregon

14818

Dependent Resurvey, Portion of Subdivisional Lines, T. 22 S., R. 10 W.

CHAINS

2 ft. high, mkd. X on bedrock at base, from which the remaining original bearing tree:

A fir, 22 ins. diam., bears N. 88° E.  
43 lks. dist., with fragmentary scribe marks visible on partially open blaze.

and bearing trees mkd. by the Oregon State Board of Forestry

A fir, 17 ins. diam., bears N. 26 1/4° E.,  
30 1/2 lks. dist., with fragmentary scribe marks visible on partially open blaze.

A fir, 15 ins. diam., bears S. 62 1/2 W.,  
4 1/2 lks. dist., with fragmentary scribe marks visible on partially open blaze.

A fir, 15 ins. diam., bears N. 43° W.,  
16 lks. dist., with fragmentary scribe marks visible on partially open blaze.

At the corner point

Set a brass tablet, 3 1/4 ins. diam., 3 1/2 ins. stem, in drill hole, in solid rock, with top mkd.

T 22 S R 10 W  
S 23 | S 24  
S 26 | S 25  
1970

Land, mountainous.  
Soil, rocky clay loam.  
Timber, fir, hemlock, cedar, oak, maple, alder, and dogwood; undergrowth, salal, hazel, poison oak, Oregon grape, and vine maple.

From the cor. of secs. 19, 24, 25, and 30.

N. 87° 52' W., bet. secs. 24 and 25

Ascend 445 ft. over NE. slope, through heavy timber and dense undergrowth.

40.80 Spur ridge, bears N. 70° E., and S. 70° W.; desc. 5 ft. over W. slope.

41.31 Point for the 1/4 sec. cor. of secs. 24 and 25, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

1/4 S 24  
S 25  
T 22 S R 10 W  
1970

from which

A hemlock, 15 ins. diam., bears N. 25° E.,  
108 lks. dist., mkd. 1/4 S24 BT.

A hemlock, 26 ins. diam., bears S. 21 1/4° E.,  
27 1/2 lks. dist. mkd. 1/4 S25 BT.

Descend 165 ft. over broken NW. slope.