

# County Surveyor's Record, Douglas County, Oregon

14850

Dependent Resurvey, Portion of Subdivisional Lines, T.22 S., R. 10 W.

CHAINS

and a tree of no record

A fir, 23 ins. diam., bears S. 81° E.,  
24 lks. dist., with fragmentary scribe  
marks visible on partially opened blaze.

Ascend 55 ft. over SE. slope.'

42.25 Spur, slopes S. 80° E.; desc. 530 ft. over NE. slope.

58.85 Paved road, 30 lks. wide, bears N. 65° W. and S. 65° E.

60.45 Mill Creek, 100 lks. wide, course N. 45° W.; asc. 230  
ft. over SW. slope.

67.60 Spur, slopes S. 60° W.; desc. 15 ft. over N. slope.

68.75 Ravine, drains N. 80° W.; asc. 185 ft. over SW. slope.

78.82 The cor. of secs. 26, 27, 34, and 35, determined at  
record bearing and distance from the remaining original  
bearing trees:

A fir, 40 ins. diam., bears S. 70° E.,  
8 lks. dist. with fragmentary scribe marks  
visible on partially open blaze.

A fir, 40 ins. diam., bears S. 8° W.,  
35 lks. dist., with healed blaze.

A fir, 44 ins. diam., bears N. 14° W.,  
68 lks. dist., with healed blaze.

and a tree of no record

A fir, 42 ins. diam., bears N. 76° E.,  
45 lks. dist., with healed blaze.

At the corner point

Set an ironpost, 28 ins. long, 2 1/2 ins. diam., 24 ins  
in the ground, with brasscap mkd.

T	22	S	R	10	W
	S	27		S	26
	S	34		S	35
	1970				

from which a new bearing tree

A fir, 14 ins. diam., bears N. 8° E.,  
54 lks. dist., mkd. T22S R10W S26 BT.

Land, mountainous.

Soil, rocky cly loam.

Timber, fir, hemlock, cedar, oak, maple, alder, and  
dogwood; undergrowth, salal, hazel, vine maple, poison  
oak, and fern.

From the cor. of secs. 25, 26, 35, and 36.

S. 89° 25' W., bet. secs. 26 and 35.

Ascend 515 ft. over SE. slope, through scattering timber  
and dense undergrowth.

12.95 Dirt road, 10 lks. wide, bears N. 10° E. and S. 10° W.

28.85 Spur, slopes N. 30° E.; desc. 220 ft. over W. slope.