

# County Surveyor's Record, Douglas County, Oregon

14838

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 24 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

cedar, dogwood, and maple; undergrowth, salal, hazel, fern, poison oak, and vine maple.

N. 0° 09' E., bet. secs. 26 and 27.

Ascend 210 ft. over NW. slope through scattering timber and light undergrowth.

15.00 Dirt road, 15 lks. wide, bears N. 60° W. and S. 60° E.

15.20 Woven wire fence, bears N. 60° W. and S. 60° E.,

17.60 Barbed wire fence, bears E. and W.; enter moderate timber and dense undergrowth.

30.75 Spur ridge, bears NE. and SW.; desc. 100 ft. over NW. slope

40.10 The 1/4 sec. cor. of secs. 26 and 27, perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1963, monumented with an iron pipe, 2 ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 24 S  
S | S  
27 | 26  
R 4 W  
1963

from which the remains of the original bearing trees

A root hole, bears N. 75° E., 38 lks. dist.

A fir snag, 36 ins. diam., bears S. 57° W.,  
32 lks. dist., no marks visible.

and bearing trees marked by Godfrey

A black oak, 12 ins. diam., bears N. 14° E.,  
36 lks. dist., with healed blaze.

A fir, 10 ins. diam., bears N. 46° W.,  
26 lks. dist., with healed blaze.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, alder, madrone, white oak, black oak, cedar, dogwood, and maple; undergrowth, salal, hazel, fern, poison oak, and vine maple.

From the cor. of secs. 26, 27, 34 and 35.

N. 89° 30' W., bet. secs. 27 and 34.

Ascend 260 ft. over SE. slope, through open field.

0.40 Dirt road, 15 lks. wide, bears N. and S.

5.85 Enter moderate timber and dense undergrowth, edge bears N. and S.

19.00 Barbed wire fence, bears N. 20° E., and S. 20° W.; also spur ridge, bears same; desc. 190 ft. over NW. slope.

31.20 Creek, 1 lk. wide, course N.; asc. 115 ft. over NE. slope.