

County Surveyor's Record, Douglas County, Oregon

14865

Dependent Resurvey, Portion of Subdivisional Lines, T. 26S., R. 7 W.

CHAINS	
	<p>A fir, 4 ins. diam., bears N. 81° W., 37 lks. dist., mkd. X BT.</p> <p>Add marks B L M to brass cap.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, cedar, maple, oak, tan oak, myrtle, and chinquapin; undergrowth, salal, rhododendron, Oregon grape, hazel, fern, poison oak, and vine maple.</p>
	<p>From the cor. of secs. 17, 18, 19, and 20.</p> <p>N. 0° 26' E., bet. secs. 17 and 18.</p> <p>Descend 545 ft. over N. slope, through moderate timber and dense undergrowth.</p>
19.97	<p>Point for the S 1/16 sec. cor. of secs. 17 and 18.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 1/16 S 18 S 17 1969</p>
	<p>from which</p> <p>A fir, 29 ins. diam., bears N. 42 1/2° E., 83 1/2 lks. dist., mkd. S 1/16 S17 BT.</p> <p>An alder, 6 ins. diam., bears N. 79° W., 53 lks. dist., mkd. S 1/16 S18 BT.</p> <p>Descend 30 ft. over N. slope.</p>
21.70	<p>Camp Creek, 10 lks. wide, course W.; asc. 595 ft. over SW. slope.</p>
27.60	<p>Rock bluff, 25 lks high, faces S.; continues descent over SW. slope.</p>
39.94	<p>Point for the 1/4 sec. cor. of secs. 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 26 S R 7 W 1/4 S 18 S 17 1969</p>
	<p>from which</p> <p>A madrone, 6 ins. diam., bears S. 47 1/4° E., 17 lks. dist., mkd. 1/4 S17 BT.</p> <p>A fir, 47 ins. diam., bears S. 35 1/2° W., 63 lks. dist., mkd. 1/4 S18 BT.</p> <p>Ascend 10 ft. over SW. slope.</p>
45.95	<p>Ravine, drains S. 35° W.; asc. 235 ft. over S. slope.</p>
57.80	<p>Spur slopes W.; desc. 565 ft. over NE slope.</p>