

County Surveyor's Record, Douglas County, Oregon

14879

Dependent Resurvey, Portion of Subdivisional Lines, T. 31 S., R. 6 W.

CHAINS

A madrone root crown, with sprouts, bears N.
N. 36 1/2° E., 39 1/2 lks. dist., no marks visible.

A stump hole, bears S. 49° W., 80 lks. dist.,
with a decayed and burned madrone alongside,
with scribe marks SC visible on remains of
blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the
ground, with brass cap mkd.

T 31 S R 6 W
S 2 | S 1
S 11 | S 12
1969

from which new bearing trees

A madrone, 5 ins. diam., bears N. 36 1/2° E.,
37 1/2 lks. dist., mkd. T31S R6W S1 BT.

A fir, 5 ins. diam., bears S. 18 1/4° E., 97 1/2
lks. dist., mkd. T31S R6W S12 BT.

A madrone, 5 ins. diam., bears S. 38 1/4° W.,
113 lks. dist., mkd. T31S R6W S11 BT.

A fir, 5 ins. diam., bears N. 49° W., 66 1/2
lks. dist., mkd. T31S R6W S2 BT.

The corner is located in an abandoned dirt
road, 10 lks. wide, bears N. 40° E., and
S. 40° W.

N. 0° 11' E., bet. secs. 1 and 2 .

Descend 100 ft., over NW. slope, through old logged area and dense
undergrowth.

- 4.00 Ravine, drains S. 30 ° W.; asc. 130 ft. over S. slope.
- 13.85 Spur, slopes N. 75° W.; desc. 170 ft. over N. slope.
- 18.70 Ravine, drains N. 85° W.; asc. 30 ft. over SW. slope.
- 21.70 Spur, slopes S. 75° W.; desc. 50 ft. over NW. slope.
- 26.60 Ravine, drains S. 20° W.; asc. 140 ft. over S. slope.
- 32.80 Gravel road, 15 lks. wide, bears N. 60° W. and S. 60° E.
- 38.65 Spur ridge, bears N. 70° W., and S. 70° E.; desc. 40 ft. over NE
slope.
- 39.90 Point for the 1/4 sec. cor. of secs. 1 and 2, at proportionate
distance, there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the
ground, with brass cap mkd.

T 31 S R 6 W
1/4
S 2 | S 1
1969