

# County Surveyor's Record, Douglas County, Oregon

14902

Dependent Resurvey, Portion of Subdivisional Lines, T. 22 S., R. 9 W.

CHAINS

Descend 195 ft. over broken N. slope.

24.00 Ravine, drains. N. 25° W.; asc. 110 ft. over broken SW. slope.

27.60 Top of ascent, slopes W.; desc. 55 ft. over broken N. slope.

31.75 Ravine, drains. W.; asc. 45 ft. over broken SW. slope.

34.10 Top of ascent, slopes W.; desc. 100 ft. over broken NW. slope.

38.75 Creek, 5 lks. wide, course S. 15° W.; asc. 3 ft. over SE. slope.

40.30 Point for the 1/4 sec. cor. of secs. 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

1/4  
S 18 | S 17  
T 22 S R 9 W  
1970

from which

A fir, 22 ins. diam., bears S. 72 1/2° E., 100 lks. dist., mkd. 1/4 S17 BT.

A fir, 25 ins. diam., bears N. 27 3/4° W., 38 lks. dist., mkd. 1/4 S18 BT.

Ascend 105 ft. over SE. slope.

48.50 Top of ascent, slopes SE.; desc. 115 ft. over broken NW. slope.

52.00 Dirt road, 20 lks. wide, bears N. 15° W. and S. 15° E.

60.45 Point for the N 1/16 sec. cor. of secs. 17 and 18.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

N 1/16  
S 18 | S 17  
1970

from which

A fir, 18 ins. diam., bears N. 84° E., 136 lks. dist., mkd. N 1/16 S17 BT.

A fir, 12 ins. diam., bears N. 74 1/4° W., 322 lks. dist., mkd. N 1/16 S18 BT.

Ascend 70 ft. over broken SW. slope.

64.65 Same dirt road, 20 lks. wide, bears N. 30° E. and S. 30° W.

68.75 Ravine, drains. W.; desc. 60 ft. over broken NW. slope.