

County Surveyor's Record, Douglas County, Oregon

1908

Dependent Resurvey, Portion of Subdivisional Lines,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

A root hole, bears N. $54\frac{1}{2}^{\circ}$ W., 171 lks. dist., with
a down fir alongside, 44 ins. diam., with no marks
visible on open blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the
ground, with brass cap mkd.

T 22 S R 9 W
S 6 | S 8
S 7 |
1970

and bearing trees mkd. by persons unknown

A fir stump, 19 ins. diam., bears N. $60\frac{1}{2}^{\circ}$ E., 16
lks. dist., with partial scribe marks visible
on bark blaze.

A fir, 13 ins. diam., bears S. $80\frac{1}{2}^{\circ}$ W., 29 lks.
dist., with healed blaze.

and a new bearing tree

A fir, 13 ins. diam., bears N. $50\frac{1}{2}^{\circ}$ W., 39 lks.
dist., mkd. T22S R9W S6 BT.

Land, mountainous.

Soil, clay loam.

Timber, fir, hemlock, cedar, alder, oak, and dogwood;
undergrowth, salal, Oregon grape, hazel, fern and bunch grass.

Dependent Resurvey of a Portion of the Boundaries
of Donation Land Claim No. 38, T. 22 S., R. 9 W.,
Willamette Meridian, Oregon.

(Restoring the 1856 survey by Dennis Hathorn and the
dependent resurvey by George S. Pershin in 1896.)

From the SW. cor. of Donation Land Claim No. 38, at proportionate
distance along the N. bdy. of Claim No. 37; there is no re-
maining evidence of the original corner.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the
ground, with brass cap mkd.

T 22 S |
S 18 | C 38
R 9 W |
C 37
1970

from which

An alder, 8 ins. diam., bears N. $5\frac{1}{2}^{\circ}$ E., $46\frac{1}{2}$ lks.
dist., mkd. C 38 BT.