

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 31 S., R. 8 W., Willamette Meridian, Oregon

1435

CHAINS

N. 0° 39' W., bet. secs. 7 and 8.

Ascend 270 ft. over S. slope, through heavy timber and moderate undergrowth.

5.65 Dirt road, 25 lks. wide, in curve, bears N. 75° W., and S. 85° E.

10.80 Dirt road, 20 lks. wide, bears N. 40° W., and S. 40° E.

16.85 Spur, slopes SE.; desc. 340 ft. over NE. slope.

33.45 Ravine, drains. N. 35° W.; asc. 10 ft. over NW. slope. Also timber changes to reproduction.

38.40 Spur, bears NW.; desc. 15 ft. over N. slope.

40.04 Point for the cor. of secs. 5, 6, 7, and 8, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

T 31 S R 8 W
S 6 | S 5
S 7 | S 8
1973

from which

A fir, 8 ins. diam., bears N. 37° E., 37 lks. dist., mkd. T31S R8W S5 BT.

A fir, 13 ins. diam., bears S. 22 1/2 ° E., 24 lks. dist., mkd. T31S R8W S8 BT.

A fir, 10 ins. diam., bears S. 24 1/2° W., 28 lks. dist., mkd. T31S R8W S7 BT.

A fir, 10 ins. diam., bears N. 82° W., 17 1/2 lks. dist., mkd. T31S R8W S6 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, oak, madrone, chinquapin, cedar, and pine; undergrowth, salal, huckleberry, salmonberry, live oak, hazel, rhododendron, ferns, and vine maple.

From the 1/4 sec. cor. of secs. 5 and 8, monumented with an iron post, 2 1/2 ins. diam., firmly set, protruding 6 ins. above ground, with brass cap mkd.

1/4 $\frac{S 5}{S 8}$
T 31 S R 8 W
1961

from which the remains of the original bearing trees

A stump hole, with roots of a hemlock remaining, bears East, 20 lks. dist.

A hemlock, 17 ins. diam., bears S. 85° W., 33 lks. dist., with old axe marks visible on opened blaze.

and bearing trees marked by White, Corbin, and Beck.