

County Surveyor's Record, Douglas County, Oregon

14940

Dependent Resurvey, Portion of S. Bdy., T. 24 S., R. 6 W.

CHAINS

A fir snag, 35 ins. diam., bears S. $9\ 1/4^\circ$ E., 158 lks. dist., with a healed blaze. (Record, S. 6° E., 155 lks.)

A root hole, bears S. 74° W., 134 lks. dist., with a rotted oak, 18 ins. diam. alongside, with no marks visible. (Record, 136 lks.)

and bearing trees mkd. by B. B. Irving, County Surveyor in 1947

A fir snag, 20 ins. diam., bears N. $73\ 12/^\circ$ E., 42 lks. dist., with scribe marks T24S R6W S32 CS BT visible on bark.

A fir, 20 ins. diam., bears S. $35\ 3/4^\circ$ E., 102 lks. dist., with a healed blaze.

A fir, 21 ins. diam., bears S. $6\ 1/4^\circ$ W., 98 lks. dist., with a healed blaze.

A fir stump, 20 ins. diam., bears N. 2° W., 92 lks. dist., with no marks remaining.

and bearing trees mkd. by the County Surveyor in 1962

A fir, 8 ins. diam. bears N. 20° E., 179 lks. dist., with a healed blaze.

A fir, 21 ins. diam., bears S. 77° E., 82 lks. dist., with a healed blaze.

A fir, 32 ins. diam., bears N. $66\ 1/2^\circ$ W., 95 lks. dist., with a healed blaze.

The corner of wire fences extending E. and S., bears N. 60° W., 36 lks. dist.

S. $89^\circ\ 53'$ W., bet. secs. 6 and 31, marking and blazing the true line.

Ascend 170 ft. over E. slope, through medium timber and dense undergrowth, across partially logged area.

0.32 Wire fence, bears N. and S.

7.40 Spur, slopes SE.; desc. 40 ft. along broken S. slope.

25.20 Creek, 2 lks. wide, course S. 60° E.; asc. 405 ft. over NE. slope changing to E. slope.

40.00 Point for the $1/4$ sec. cor. of secs. 6 and 31, on the S. bdy. of the Tp., at record distance in departure; there is no remaining evidence of the original corner.'

Set an iron post, 28 ins. long, $2\ 1/2$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 24 S R 6 W
 $1/4\ \frac{S\ 31}{S\ 6}$
 T 25 S
 1967

from which

A fir, 15 ins. diam., bears N. $14\ 3/4^\circ$ W.,