

# County Surveyor's Record, Douglas County, Oregon

14943

Dependent Resurvey, Portion of W. Bdy., T. 24 S., R. 6 W.

CHAINS

A root hole, bears S. 52 1/2° W., 45 lks. dist.

A burned and shattered fir stump, 25ins. diam., bears N. 50° W., 34 lks. dist., with lower portion of burned blaze visible.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins in the ground, with brass cap mkd.

T 24 S	T 24 S
R 7 W	R 6 W
S 36	S 30
	S 31
	1967

from which a new bearing tree

A fir, 13 ins. diam., bears S. 68° E., 110 lks. dist., mkd. T24S R6W S31 BT.

The corner falls in head of ravine, drains SE.

Land, mountainous.

Soil, rocky clay with rock outcroppings.

Timber, fir, hemlock, cedar, madrone, dogwood, chinquapin, alder, yew, and maple; undergrowth, young timber, fern, salal, vine maple, huckleberry, Oregon grape, poison oak, hazel, arrowwood, and salmonberry.

North, on the W. bdy. of sec. 30.

Ascend 36 ft. over SE. slope, through medium timber and dense undergrowth, across partially logged area.

1.71

Intersect the original closing cor. of secs. 25 and 36, on the E. bdy. of T. 24 S., R. 7 W., determined at record bearing and distance from the original bearing trees:

A fir stump, 40 ins. diam., bears S. 40° E., 35 lks. dist., with no marks remaining.

A root hole, bears S. 28° W., 19 lks. dist., with an uprooted fir, 40 ins. diam., alongside, with no marks visible on burned out blaze.

A cedar, 24 ins. diam., bears N. 68 1/2° W., 39 lks. dist., with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins in the ground, with brass cap mkd.

	T 24 S	T 24 S
	R 7 W	R 6 W
	S 25	S 30
CC	S 36	
	1967	

from which a new bearing tree

A fir, 38 ins. diam., bears S. 43 1/4° W., 98 lks. dist., mkd. T24S R7W S36 CC BT.