

County Surveyor's Record, Douglas County, Oregon

14944

Dependent Resurvey, Portion of W. Bdy., T. 24 S., R. 6 W.

CHAINS

- Ascend 18 ft. over SE. slope.
- 6.25 Spur, slopes N. 75° E.; desc. 210 ft. over NE. slope.
- 14.10 Bottom of descent, slopes E.; asc. 80 ft. over SE. slope.
- 18.65 Rocky point, slopes E.; desc. 10 ft. over NE. slope.
- 20.50 Head of ravine, drains SE.; asc. 115 ft. over SE. slope.
- 23.85 Spur, slopes E.; desc. 105 ft. over NE. slope.
- 27.70 Spur ridge, bears N. 20° E. and S. 20° W.; desc. 160 ft. over NW. slope.
- 39.98 The 1/4 sec. cor. of sec. 30 only, monumented with an iron post, 1 in. diam., protruding 18 ins. above ground, firmly set, with brass cap mkd. and witnessed as described in the official record of a 1962 resurvey.

Land, mountainous.
 Soil, rocky clay with rock outcroppings.
 Timber, fir, hemlock, cedar, madrone, yew, dogwood, alder, maple, and chinquapin; undrgrowth, young timber, fern, salal, vine maple, ceanothus, and poison oak.

Genereal Description

The lines resurveyed are located on Tye Mountain about eight miles northwest of Sutherlin, Oregon. Elevation ranges from about 1100 feet above sea level to about 2400 feet above sea level. The area is well watered and has a soil of rocky clay sutied to the growth of timber, which is predominately fir with a scattering of hemlock cedar, yew, madrone, chinquapin, dogwood, alder, maple, and oak. Undergrowth consists of young timber, fern, salal, huckleberry, hazel, arrowwood, poison oak, vine maple, Oregon grape, salmonberry, ceanothus, and blackberry.

There were no dwellings or other improvements along the lines resurveyed. Road building and logging were the only activities noted in the area.

No mineral deposits were noted.

The average of several readings along the lines resurveyed gives a value of 19° 45' East for t amean magnetic declination. There is a range of 1° 00' in local attraction.