

# County Surveyor's Record, Douglas County, Oregon

1947

Dependent Resurvey, Portion of E. Bdy., T. 25 S., R. 7 W.,

CHAINS

T 25 S  
R 7 W | R 6 W  
S 13 | S 18  
S 24 | S 19  
1968

from which

A madrone, 38 ins. diam., bears N. 49° E., 134 lks. dist.,  
mkd. T25S R6W S18 BT.

A fir, 13 ins. diam., bears S. 59° E., 190 lks.  
dist., mkd. T25S R6W S19 BT.

A fir, 7 ins. diam., bears S. 80° W., 74 lks.  
dist., mkd. T25S R7W S24 BT.

A fir, 17 ins. diam., bears N. 54° W., 95 lks.  
dist., mkd. T25S R7W S13 BT.

Land, broken foothills.

Soil, clay.

Timber, fir, oak, madrone, maple, and alder; undergrowth,  
poison oak, fern, salal, blackberry, hazel, and wild  
rose.

N. 0° 06' W., bet. secs. 13 and 18.

Ascend 730 ft. over steep SW. slope, through heavy young  
timber and dense undergrowth, across partially logged  
area.

20.15 Rocky spur, slopes S. 40° E.; asc. 195 ft. along E.  
slope changing to SE. slope.

30.50 Rocky spur, slopes S. 75° E.; desc. 110 ft. over NE. slope.

34.50 Ravine, drains S. 75° E.; asc. 145 ft. over rocky  
SE. slope.

38.36 The  $\frac{1}{4}$  sec. cor. of secs. 13 and 18, perpetuated and recorded  
by the County Surveyors Office in 1963, monumented with an  
iron post, 1 in. diam., protruding 12 ins. above ground,  
firmly set, with brass cap mkd.

T 25 S  
R 7 W | R 6 W  
 $\frac{1}{4}$  S 13 | S 18  
1963

from which the original bearing trees:

A root hole, bears N. 82° E., 64 lks. dist.,  
with an uprooted fir, 36 ins. diam., along-  
side with axe marks visible.

A fir, 37 ins. diam., bears N. 2° W., 150 lks.  
dist., with scribe marks  $\frac{1}{4}$  visible on bark.

and bearing trees mkd. by the County Surveyor in 1963

A fir, 23 ins. diam., bears N. 1° E., 13 lks.  
dist., with scribe marks  $\frac{1}{4}$  S18 CS BT  
visible on open blaze.

A fir, 16 ins. diam., bears S. 85° W.,  
32 lks. dist., with scribe marks  $\frac{1}{4}$  S13  
CS BT visible on open blaze.