

County Surveyor's Record, Douglas County, Oregon

1951

Dependent Resurvey, Portion of N. Bdy., T. 25 S., R. 7 W.

CHAINS

FND. OK 10/94 BY SMALLBY
C.S. 63/154

T 24 S R 7 W
S 35 | S 36
S 2 | S 1
T 25 S R 7 W
1967

from which

A fir, 17 ins. diam., bears N. 59° E., 13 lks.
dist., mkd. T24S R7W S36 BT.

A fir, 25 ins. diam., bears S. 16¼° E., 57 lks.
dist., mkd. T25S R7W S1 BT.

A fir, 17 ins. diam., bears S. 29½° W., 31½ lks.
dist., mkd. T25S R7W S2 BT.

A fir, 43 ins. diam., bears N. 50½° W., 183
lks. dist., mkd. T24S R7W S35 BT.

Land, mountainous.

Soil, rocky clay with rock outcroppings.

Timber, fir, cedar, hemlock, madrone, alder, maple, yew,
and chinquapin; undergrowth, young timber, fern, salal,
Oregon grape, poson oak, hazel, arrowwood, manzanita,
thimbleberry, ceanothus, salmonberry, vine maple, and
blackberry.

S. 89° 25' E., bet. secs. 1 and 36.

Ascend 485 ft. over broken SW. slope, through heavy
timber and dense undergrowth.

40.08 Point for the ¼ sec. cor. of secs. 1 and 36, at proportionate
distance; there is no remaining evidence of the
original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.
in the ground, with brass cap mkd.

T 24 S R 7 W
¼ S 36
S 1
T 25 S
1967

from which

A cedar, 25 ins. diam., bears N. 59° W., 62½ lks.
dist., mkd. ¼ S36 BT.

A fir, 22 ins. diam., bears S. 84° E., 57½ lks.
dist., mkd. ¼ S1 BT.

Descend 50 ft. over SE. slope.

44.25 Creek, 2 lks. wide, course S. 20° W.; asc. 300 ft. over
broken SW. slope changing to NW. slope, along creek,

59.25 Creek, 1 lk. wide, course N. 60° W.; asc. 375 ft. over
SW. slope changing to W. slope.

63.60 Dirt road, 25 lks. wide, bears N. and S.

77.47 Intersect the W. bdy. of T. 24 S., R. 6 W.

True point for the closing cor. of Tps. 24 and 25 S.,
R. 7 W.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.